

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8703S

DATE 23..07.2021

MAKE HYUNDAI

MVA CHIANG/ AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			<i>Rp</i> \$1,160.00
1	REAR BUMPER SIDE BRACKET RH			<i>X</i> \$35.60
1	REAR WHEEL CAP RH			<i>X</i> \$217.20
	SUB TOTAL			<i>old damage</i> \$1,412.80
	20.00%			\$282.56
	DISCOUNTED TOTAL			\$1,130.24
1	REAR DOOR COMFORT APP STICKER			<i>new</i> \$80.00
				\$80.00
	Labour Charge			
	Panel Beating		<i>280</i>	\$300.00
	Spray Painting Charge		<i>750</i>	\$800.00
	Tuff coat		<i>X</i>	\$90.00
	TOTAL LABOUR			\$1,190.00
	ESTIMATE TOTAL			\$2,400.24
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Taufik 97495749
 WP' 20/7/21 @ 1630
 L/S Resurvey After repair
 Taufik cllkauto.com
 2 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 24.07.2021 10:13

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305479649

MEMER

COMFORT TRANSPORTATION PTE LTD

7010045

MEMER NO.

383 SIN MING DRIVE

ESS

Singapore SINGAPORE 575717

65508755

(O)

(R)

(P)

JUNT CARD NO.

REGN NO.: SHC8703S

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL I-40

DATE/TIME IN 23.07.2021 11:35

YR OF MANU 19.11.2015

TARGET DATE

CHASSIS CODE KMHLB41UMGU080583

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 23.07.2021

NATURE: 3P 23.07.2021

S/NO

LABOR CODE

DESCRIPTION



OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

No.:

SHC8703S

CHIANG

Vehicle No.: *

SHC8703S

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard