

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date :17/07/2021

Estimated repair cost for vehicle no: SLX11A TOYOTA ALPHARD 2.5 CVT ELEGANCE

CHASSIS: JTNGF3DH508003617 (2015)

TP At Cap
Justin.

24/07/2021

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Delud</i>	\$1,791.30	\$1,791.30 ✓ 870
2	1	REAR BUMPER SIDE RETAINER LH <i>auhd</i>	\$85.60	\$85.60 ✓
3	1	REAR BUMPER CORNER LH <i>Delud</i>	\$512.30	\$512.30 ✓ 385
4	1	REAR BUMPER CORNER SIDE RETAINER LH <i>auhd</i>	\$81.60	\$81.60 ✓
5	1	REAR BUMPER REVERSE SENSOR <i>Delud</i>	\$321.60	\$321.60 ✓
6	1	REAR BUMPER REVERSE SENSOR COVER <i>new</i>	\$68.40	\$68.40 ✗
7	1	REAR BUMPER REFLECTOR LH <i>new</i>	\$154.10	\$154.10 ✗
8	1	REAR END PANEL (INNER) <i>3 Pags</i>	\$595.40	\$595.40 ✗
9	1	REAR END PANEL (OUTER) <i>3 Pags</i>	\$799.10	\$799.10 ✗
10	1	REAR TAILLAMP LH <i>cut</i>	\$1,248.60	\$1,248.60 ✓ 685
11	1	REAR TAILLAMP LOWER BARCKET LH <i>new</i>	\$68.40	\$68.40 ✗
12	1	REAR BUMPER UNDER COVER <i>new</i>	\$145.60	\$145.60 ✗
13	1	REAR TAILGATE LAMP LH <i>cut</i>	\$446.40	\$446.40 ✓
14	1	LH REAR FENDER <i>Pags</i>	\$1,998.70	\$1,998.70 ✗
15	1	LH REAR FENDER INNER COWLING <i>3 new</i>	\$180.60	\$180.60 ✗
16	1	LH REAR SLIDING DOOR	\$2,148.60	\$2,148.60 ✗

287520
215640

TOTAL :	\$10,646.30
LESS 25 %	\$2,661.58
SUB-TOTAL :	\$7,984.73

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>Ren</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR END PANEL SEALANT <i>Ren</i>	\$80.00	\$80.00 <i>+</i>

30

TOTAL: \$160.00

TOTAL PARTS: \$8,144.73

Labour charges

1	LABOUR FOR PANEL BEATING	<i>101330</i>	\$1,200.00 <i>450</i>
2	LABOUR FOR SPRAYPAINTING		\$1,000.00 <i>80</i>
3	WIRING CHECK		\$80.00 <i>30</i>
4	LABOUR FOR REMOVE & REFIX REAR UPHOSLTERY /ROOF LINING		\$300.00 <i>+</i>
5	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS		\$200.00 <i>50</i>
6	LABOUR FOR REMOVE & TRANSFER LH REAR SLIDING DOOR FITTING		\$300.00 <i>+</i>

Subtotal :- \$3,080.00

Total:- \$11,224.73

Adrian Ly
L/S 13/10/21
030 days.

total: 351640

L/S: 2.8k.

2.8k

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: