

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21007921/KPA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100488112
<b>Claimant Vehicle No :</b>	SKG4549R	<b>Insured Vehicle No :</b>	SLH2346E
Date of Loss:	21/07/2021	Nature of Claim:	TP
		Claim No:	8547220885SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKG4549R</b>	Engine No:	G4FGBU308026
Make & Model:	HYUNDAI ELANTRA, 1.6 D/AB 2WD 4DR (A)	Chassis No:	KMHDH41CMCU250896
Reg. Date:	11/10/2011 (Man. Year: 2011)	Odometer:	150946 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	GREEN-MAX 7 mm	Rear Left Side:	GREEN-MAX 8 mm
Front Right Side:	GREEN-MAX 7 mm	Rear Right Side:	GREEN-MAX 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,483.76	1,803.68	1,680.08	48.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	670.00	510.00	43.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,663.76</b>	<b>2,473.68</b>	<b>2,190.08</b>	<b>46.96</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	4,663.76	1,300.00	3,363.76	72.13
<b>+ GST 7.00/7.00% (S\$)</b>	326.46	91.00	235.46	72.13
<b>Nett Amount (S\$)</b>	<b>4,990.22</b>	<b>1,391.00</b>	<b>3,599.22</b>	<b>72.13</b>
<b>+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		428.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,821.00</b>		

INSPECTION

Date of Assignment:	26/07/2021	Chew Goon Motor (AMK)
Date Inspected:	27/07/2021 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	3.0 days	Singapore 568047

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	521.00 FL	*474.60 FL
2	10		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*FRONT BUMPER TOP RETAINER LH	Serviceable	13.00 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Serviceable	121.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	550.00 FL	*- FL
6	1		*FRONT BUMPER BRACKET LH	Repair	25.00 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP LH	Cut	267.70 FL	*267.70 FL
8	1		*FRONT BUMPER CORNER RETAINER LH	Serviceable	25.00 FL	*- FL
9	1		*HEADLAMP LH	Cut	1,822.00 FL	*1,482.30 FL
10	1		*HEADLAMP LOWER PANEL LH (FIBER)	Serviceable	980.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,354.70	2,254.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	870.94	450.92
Total Parts (\$\$)	3,483.76	1,803.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
2	TO REMOVE/REFIT ,RADIATOR SYSTEM ,BLEED ,REFILL COOLANT TO FACILITATE REPAIR	New	80.00	0.00
3	TO REMOVE/REFIT AIR CON CONDENSER & REFILL AIR CON GAS TO FACILITATE REPAIR	New	120.00	0.00
4	LABOUR CHARGE-PANEL BEATING ,FRONT N/S FENDER AND PARTS REPLACEMENT	New	400.00	250.00
5	TO RESPRAY AFFECTED AREAS	New	550.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>1,180.00</b>	<b>670.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >