

Hsiao Dong

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No:

SJQ4519L

Model and make:

Toyota Vios

2009

Qty Spare parts

List price

1	Bootlid	\$	✓ 618.20	BT✓
1	Bootlid "Vios" emblem	\$	✓ 49.30	
1	Bootlid centre logo	\$	✓ 45.70	NEC✓
1	Bootlid "G" emblem	\$	✓ 29.90	
1	Bootlid RH hinge	\$	96.80	
1	Bootlid LH hinge	\$	96.80	NDX
1	Bootlid lock	\$	✓ 211.70	JM✓
1	Bootlid lock catch	\$	48.00	NDX
1	Bootlid chrome moulding	\$	✓ 241.00	DL
1	Rear bumper	\$	380.20	561.80 BR✓
1	Rear bumper RH side retainer	\$	36.00	191.10 NEC✓
1	Rear bumper RH bracket	\$		171.45 NSX
1	Rear bumper LH side retainer	\$	36.00	191.10 NEC✓
1	Rear bumper LH bracket	\$		171.45 NSX
1	Rear bumper RH reflector	\$	35.70	178.85 BR✓
1	Rear bumper LH reflector	\$	35.70	178.85
1	Rear bumper RH splash shield	\$		98.70 NDX
1	Rear bumper LH splash shield	\$		98.70
1	RH taillamp assy	\$	288.50	✓ 342.80 BR
1	RH taillamp panel	\$		182.55 NDX
1	RH taillamp black sponge gasket	\$		✓ 43.70 TN✓
1	LH taillamp assy	\$		✓ 342.80 BR✓
1	LH taillamp panel	\$		✓ 182.55 DD✓
1	LH taillamp black sponge gasket	\$		✓ 43.70 TN✓
1	End panel	\$	517.00	791.35 DD✓
1	End panel inner garnish	\$		✓ 182.00 BR✓
1	End panel RH side bracket	\$		89.50
1	End panel LH side bracket	\$		89.50 NDX
1	Rear RH fender inner trim	\$	361.60	378.85 TN✓
1	Rear LH fender inner trim	\$	361.60	378.85
1	Floor panel	\$		981.10 NDX
1	Floor panel top board cover	\$	291.10	375.10 DD✓
1	Floor panel tool sponge centre tray	\$		285.50 NSX
1	Floor panel tool sponge tray RH	\$		✓ 285.50
1	Floor panel tool sponge tray LH	\$		✓ 285.50 BR✓
1	Spare tyre lock screw	\$		45.10 NDX
1	Exhaust silencer	\$		781.10 BTRX
1	Exhaust silencer gasket	\$		63.70 NNX

\$ 9,430.15

4959.25

@25%

1239.81

3719.44

-25% \$ 2,357.54
\$ 7,072.61

Qty Spare parts

Special Nett price

1set Bootlid chrome moulding clips
1set Rear bumper clips
1set Rear bumper reverse sensor
1 Rear bumper top chrome moulding
1set Rear RH fender inner trim clips
1set Rear LH fender inner trim clips
1 End panel joint sealant
1 Spare tyre panel joint sealant
1 Rear number plate

\$ ~~50.00~~ NNX
\$ 30.00 70.00 NEC✓
\$ 200.00 280.00 SC
\$ ~~280.00~~ RPTX
\$ 20.00 60.00 } NEC✓
\$ 20.00 60.00 }
\$ ~~60.00~~ NNX
\$ ~~60.00~~ NNX
\$ ~~70.00~~ NDX
270.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 600.00 1,100.00 ✓

Spray painting on affected panels

\$ 600.00 1,000.00 ✓

Check wiring and lighting system

\$ ~~80.00~~ NNX

Apply rust coating chemical on affected panels

\$ ~~80.00~~ NNX

Remove and replace rear bumper reverse sensors

\$ 60.00 70.00 NEC✓

Remove and replace rear inner trims, garnish and boards to assist repair

\$ 100.00 220.00 ✓

Remove and replace exhaust silencer and gasket

\$ 60.00 100.00 ✓

Survey & Resurvey

on 26/7/2021

1430hrs

TGim

Total: \$ 10,712.61

1420.00

Lump sum repair
Repair days 5

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts 3719.44

SN 270.00

Labour 1420.00

5409.44

1081.89

4327.55

@20%

COR LS 4300/2

TGim