



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 7263B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REAR BUMPER SPRAY PAINT.		300.00	200.00
	SIDE FENDER SPRAY PAINT.		300.00	200.00
	RIGHT REAR DOOR SPRAY PAINT.		300.00	200.00
	RIGHT REAR RIM REPLACEMENT.	NOT NECESSARY	550.00	-
	RIGHT REAR TYRE REPLACEMENT.	NOT NECESSARY	105.00	-
	LABOUR TO REMOVE / REFIT / REPLACED BUMPER, FENDER AND DOOR.		500.00	200.00
	LABOUR TO REMOVE / REFIT / REPLACED TYRES AND RIMS.		80.00	50.00
			2,135.00	850.00
	GRAND TOTAL		2,135.00	850.00

RECOMMENDED COST OF REPAIRS			850.00
------------------------------------	--	--	---------------

Report Ref No. CS/ASM21007931/Etce2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.