



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS/ASM21007931/Etce2 Date: 03/08/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 7671A	Veh. Inspected	SJH 7263B	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M03E06	Excess (\$)	0.00	
Assign From	TAN JUN HONG	Assign Date	26/07/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA COROLLA FIELDER	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1419068159	Colour	BLACK	
Odometer	244454 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	RADIAL	4 mm	
L/H Front Tyre	205/55 R16	RADIAL	4 mm	
R/H Rear Tyre	205/55 R16	RADIAL	4 mm	
L/H Rear Tyre	205/55 R16	RADIAL	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/07/2021	Inspection Date	27/07/2021	
Survey held at	RICKY TEO BATTERY & TYRES TRADING BLK 1002 BUKIT MERAH LANE 3 #01-91 SINGAPORE 159719			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	