



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Subramaniam Mohanamooty	Cust No/Name /Mr Subramaniam Mohanamooty
101 CASHEW ROAD #15-02	Reg No/Reg Date SJU3382Z / 21/03/201
#03-51	Date In/Mileage / 0
SINGAPORE 679672	Chassis No KNAFZ411MJ5761845
Contact No Mobile: 96518438	Engine No G4FGHH692039
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	26/07/2021/ 12:20	Bod	442 / Cocolu	36650			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								20.00
Sundry								
E PNT88000								2360 3600.00
RENEW FRT DOOR RH, REAR DOOR RH, SIDE SKIRT RH, REAR FENDER RH					5-5	400	+ 1/0	
I REAR BUMPER, REAR AIRDAM								2100.00
E PNT98000								
SPRAY PAINT FOR FRT DOOR RH, REAR DOOR RH, SIDE SKIRT RH, REAR FENDER RH					6	350		
I REAR BUMPER, REAR AIRDAM								100.00
E PNT88000								100.00
REMOVE & INSTALL SIDE SKIRT								
E PNT88000								60.00
REMOVE & INSTALL REAR AIRDAM								
E PNT88000								120 180.00
REMOVE & INSTALL PARKING SENSOR								
E PNT88000								120 180.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT88000								300.00
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS								
E PNT88000								
REMOVE & INSTALL REAR WINDSCREEN TO FACILITATE REPAIR								80 300.00
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION REAR WINDSCREEN								80 300.00
E PNT88000								120.00
REMOVE & INSTALL REAR FENDER INNER TRIMS (photo)								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
APPLY SEALANT FOR ACCIDENT PORTION								
A 90000001								120 280.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								30.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-1

Invoice Name & Address	Owner Name & Vehicle Info
Mr Subramaniam Mohanamoothy 101 CASHEW ROAD #15-02 #03-51 SINGAPORE 679672 Contact No Mobile: 96518438	Cust No/Name /Mr Subramaniam Mohanamoothy Reg No/Reg Date SJU3382Z / 21/03/201 Date In/Mileage / 0 Chassis No KNAFZ411MJ5761845 Engine No G4FGHH692039 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	26/07/2021/ 12:20	Bod	442 / CocoLu	36650
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
TRANSFER REAR RIGHT RIM					
M SUNDRY					20.00
Sundry					
A 90000001					300.00
RENEW REAR UNDER CARRIAGE					
M NEW K3 METAL STREAM MST	BR (rear & RH)	1.00	1177.00	00.00	1177.00
M PANEL ASSY-FRONT DOOR, RH	DD	1.00	1542.00	00.00	1542.00
M HINGE ASSY-DOOR UPPER, RH	Xnn	1.00	26.00	00.00	26.00
M HINGE ASSY-REAR DOOR UPPER, RH	Xnn	1.00	33.00	00.00	33.00
M PANEL ASSY-REAR DOOR, RH	DD	1.00	1361.00	00.00	1361.00
M PANEL ASSY-QUARTER OUTER, RH	DD	1.00	1213.00	00.00	1213.00
M HANDLE ASSY-DOOR OUTSIDE	Cut (FRONT)	1.00	214.00	00.00	214.00
M COVER-FR DR O/S HDL, DRIVER	Cut	1.00	22.00	00.00	22.00
M STRIKER ASSY-DR	Xnn	1.00	16.00	00.00	16.00
M BASE ASSY-FR DR O/S HANDLE RH	Xnn	1.00	52.00	00.00	52.00
M LATCH ASSY-FRONT DOOR, RH	Xnn	1.00	253.00	00.00	253.00
M W/STRIP ASSY-RR DR BELT O/S RH	Xnn	1.00	89.00	00.00	89.00
M GLASS-REAR DOOR FIXED, RH	Xnn	1.00	91.00	00.00	91.00
M BLACK TAPE-FR DR FRAME UPR, RH	ncc	1.00	13.00	00.00	13.00
M BLACK TAPE-FR DR RR, RH	ncc	1.00	12.00	00.00	12.00
M TAPE-RR DR FRAME BLACK RR, RH	ncc	1.00	8.00	00.00	8.00
M BLACK TAPE-RR DR FRAME UPR, RH	ncc	1.00	11.00	00.00	11.00
M WHEEL ASSY-ALUMINIUM	Cut (Rear RH)	1.00	981.00	00.00	981.00
M HUB ASSY-RR WHEEL	Xnn	1.00	340.00	00.00	340.00
M TORSION AXLE COMPLETE	Xnn	1.00	1096.00	00.00	1096.00
M SHOCK ABSORBER ASSY-REAR	Xnn	1.00	231.00	00.00	231.00
M GUARD ASSY-REAR WHEEL, RH	Xnn	1.00	75.00	00.00	75.00
M COVER-RR BUMPER	X R	1.00	688.00	00.00	688.00
M BRACKET-RR BUMPER SIDE MTG, RH	Xnn	1.00	29.00	00.00	29.00

Estimate

Steve (LKK)
27/7/21

12.0000

OD- ALI AL
EXCERS - ?

PIP, Py G.L.S.

12 dys

Confirm & accepted by _____
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on 17,493.00
Total Payable 18,717.51

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.