

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Abu Kassim, Noor Mariesa

Date: 06 Aug 2021

Preliminary Advice

Vehicle No	: SLF357Y	Accident Date	: 01/07/2021
Make	: MERCEDES-BENZ C200	Policy No.	: 0999993660
Assignment Date	: 26/07/2021	Excess	: S\$1,700.00
Date of Inspection	: 27/07/2021	Est. Duration of Repair	: 12
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,004.35
Revised Amount	:S\$	34,183.40
Check Items (Estimated)	:S\$	166.10
Total	:S\$	34,349.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00 (due to this is AMG model)
COE / PARF Rebate	:S\$	71,059.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,941.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$38,000.00 ON PART BY PART BASIS.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.