

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 6 August 2021 4:37 pm
To: tlauto@singnet.com.sg
Cc: SUR
Subject: RE: AIG-OD SLF 357Y DOA: 01/07/2021
Attachments: SLF357Y revised estimate & parts supplementary.pdf

Dear Candy,

Please proceed the supplementary as attached with our surveyor's marking.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 28 July 2021 1:05 pm
To: tlauto@singnet.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: AIG-OD SLF 357Y DOA: 01/07/2021

Dear Candy,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SLF 357Y (Excess \$1,700/-)**.

Please take note that the further supplementary and check items, we need get further approval from our principle.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey of before paint for all panels and parts.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

