



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)

DATE : 26/07/2021

POLICY NO : 999995580

VEH REG NO : SLF357Y

MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)

CHASSIS NO : WDD2050422R213804

ENGINE NO : 27492030729390

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Front windscreen glass	1	CM 660.00	660.00 ✓
2 Dashboard assy	1	Tn 2,495.00	2,495.00 ✓
3 Steering air bag	1	Amey 1,450.00	1,450.00 ✓
4 Passenger air bag	1	u 1,450.00	1,450.00 ✓
5 Knee air bag	1	u 850.00	850.00 ✓
6 Airbag control unit	1	Am 680.00	680.00 ✓
7 Airbag sensor	1	Am 155.00	155.00 ✓
8 Front safety belt - RH / LH	2	Tn 560.00	1,120.00 ✓
9 Rear safety belt - RH / LH	2	Tn 350.00	700.00 ✓
10 Bonnet	1	Bz 1,200.00	1,200.00 ✓
11 Bonnet centre logo	1	Am 58.00	58.00 ✓
12 Bonnet insulator	1	Am 185.00	185.00 ✓
13 Bonnet insulator clips	10	Am 6.50	65.00 ✓
14 Bonnet stopper - LH	1	Am 12.00	12.00 X
15 Bonnet hinge - RH / LH	2	R 135.00	270.00 ✓
16 Bonnet absorber - RH / LH	2	Am 90.00	180.00 ✓
17 Bonnet actuator - RH / LH	2	Am 192.00	384.00 X
18 Bonnet spring - RH / LH	2	Am 28.00	56.00 X
19 Bonnet center lock	1	Bz 68.00	68.00 ✓
20 Bonnet lock - LH	1	R 62.00	62.00 ✓
21 Bonnet lock switch - LH	1	Am 45.00	45.00 ✓
22 Bonnet cable - front	1	Am 58.00	58.00 ✓
23 Bonnet cable - rear	1	Am 48.00	48.00 ✓
24 Support panel	1	Am 585.00	585.00 ✓
25 Support panel top garnish	1	Am 48.00	48.00 ✓
26 Support panel top garnish clips	6	Am 5.00	30.00 ✓
27 Support panel stricker	1	Am 48.00	48.00 ✓
28 Brace panel	1	R 48.00	48.00 ✓
29 Headlamp assy - RH / LH	2	Bo 2,580.00	5,160.00 ✓
30 Headlamp bracket - LH	1	Am 65.00	65.00 ✓
31 Headlamp control unit - LH	1	CM 520.00	520.00 ✓
32 Front grille	1	CM 128.00	128.00 ✓
33 Front grille beam	1	CM 185.00	185.00 ✓

☐ Weekend (\$) Others
TOTAL



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-18
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)
DATE : 26/07/2021
POLICY NO : 999995580
VEH REG NO : SLF357Y
MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)
CHASSIS NO : WDD2050422R213804
ENGINE NO : 27492030729390
REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		SS	SS
34 Front grille beam moulding	3 x	RM/CM	312.00
35 Front grille centre logo	1	mi's	98.00
36 Front grille centre logo base	1	mi's	65.00
37 Front grille support	1	RM/CM	195.00
38 Front grille inner garnish	1	CM	95.00
39 Front bumper	1	Tn	1,080.00
40 Front bumper reinforcement	1	Rz	350.00
41 Front bumper bracket - LH	1	Rz	230.00
42 Front bumper inner carrier - RH / LH	2	CM	150.00
43 Front bumper strut - LH	1	Rz	42.00
44 Front bumper radar sensor	1	CM	780.00
45 Front bumper sponge	1	mi's	125.00
46 Front bumper centre grille	1	mi's	108.00
47 Front bumper lower inner frame	1	CM	105.00
48 Front bumper side retainer - LH	1	CM	24.00
49 Front bumper sensor	4 x	138.00	828.00
50 Front bumper sensor seal	6	RM	48.00
51 Front bumper sensor cable	1	Tn	130.00
52 Front bumper clips	15	RM	82.50
53 Front bumper tow cover	1	mi's	35.00
54 Front bumper fog lamp cover - RH / LH	2	RM/DIR	140.00
55 Front bumper fog lamp cover base - RH / LH	1	CM	68.00
56 Front bumper lower chrome - centre	1	CM	205.00
57 Rear bumper lower chrome - RH / LH	2	152.00	304.00
58 Front bumper under cover	1	168.00	168.00
59 Front bumper lower spoiler	1	WSP	120.00
60 Front number plate garnish	1	CM	98.00
61 Horn - RH / LH	2	Rz	2,970.00
62 Front fender - LH	1	Rz	555.00
63 Front fender inner shield (front) - RH / LH	2	CM	184.00
64 Front fender inner shield clips - LH	20	RM	130.00
65 Washer tank	1		98.00
66 Washer tank hose	1		53.00
67 Air-con condenser	1	Pm	950.00

Weekend (\$) Others

TOTAL

ASSIGNMENT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

C200 AMG c.c. 1991

Std / NI / NA



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)
DATE : 26/07/2021
POLICY NO : 999995580
VEH REG NO : SLF357Y
MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)
CHASSIS NO : WDD2050422R213804
ENGINE NO : 27492030729390
REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
68 Radiator assy (inner)	1	750.00	750.00
69 Radiator assy (outer)	1	680.00	680.00
70 Radiator fan motor assy	1	1,050.00	1,050.00
71 Radiator top cover	1	55.00	55.00
72 Radiator lower cover	1	122.00	122.00
73 Air duct - RH / LH	2	68.00	136.00
			32,786.50
		Add 10%	3,278.65
			36,065.15
SPECIAL NET 74 ERP bracket 1 35.00 35.00 75 Front windscreen sealant 1 60.00 60.00 76 Radiator coolant (tin) 2 40.00 80.00 77 Power steering fluid (tin) 1 92.00 92.00 267.00			
LABOUR 78 To remove and refit air-con condenser and refill air-con gas 1 150.00 150.00 79 To remove and refit radiator assy and pressure of air 1 100.00 100.00 80 To remove and refit dashboard, meter and grove box compartment to facilitates the repair 1 580.00 580.00 81 To remove and refit front windscreen glass 1 150.00 150.00 82 To dismantle and refit console box to enable replace airbag control unit 1 280.00 280.00 83 To remove and replace steering airbag, passenger airbag, knee airbag, front and rear safety belt, airbag control unit and airbag sensor 1 800.00 800.00 84 To check and rectify wiring system 1 80.00 80.00 85 To panel beat and straighten both side front fender inner panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same 1 1,800.00 1,800.00 86 To putty and spray paint on affected areas 1 1,500.00 1,500.00 87 To re-program and reset all control module faulty code 1 580.00 580.00 6,020.00			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ump Sum / L.B.I: (\$

Add Fee: ☐ Site Insp (\$
☐ Interview (\$
☐ Tech Inve (\$

Survey Fee:

Transportation:

S - RS - SI



TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg
GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)
DATE : 04/08/2021
POLICY NO : 999995580
VEH REG NO : SLF357Y
MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)
CHASSIS NO : WDD2050422R213804
ENGINE NO : 27492030729390
REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Support panel bracket - RH / LH	2	168.00 CM	336.00 ✓
2 Front bumper bracket - RH	1	230.00 B	230.00 ✓
3 Front bumper strut - RH	1	42.00 R	42.00 ✓
4 Horn brackets - RH / LH	2	45.00 R	90.00 ✓
5 Front fender - RH	1	555.00 Bu	555.00 ✓
6 Radiator top clips - RH / LH	2	12.00 M	24.00 ✓
7 Radiator vent line	1	85.00 CM	85.00 ✓
8 Radiator vent line joint	1	112.00 CM	112.00 ✓
9 Radiator lower support - RH	1	28.00 P/I	28.00 ✓
			1,502.00
		Add 10%	150.20
			1,652.20
		TOTAL	S\$ 1,652.20
		ADD GST @ 7%	115.65
		GRAND TOTAL	S\$ 1,767.85

SINGAPORE DOLLAR ONE THOUSAND SEVEN HUNDRED SIXTY-SEVEN AND CENTS EIGHTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

Report Format :
Lump Sum / I.B.I: (\$

☐ One Insp (\$
☐ Interview (\$
☐ Tech Invs (\$
☐ Weekend (\$

TOTAL