



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

*Not with insurance
Recovery B&P*

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/07/2021

*12 days
27/7/2021
2/9/2021*

ESTIMATE

NO : QUOT202107-000065(00)

DATE : 26/07/2021

POLICY NO : 999995580

VEH REG NO : SLF357Y

MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)

CHASSIS NO : WDD2050422R213804

ENGINE NO : 27492030729390

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Front windscreen glass	1	CM 660.00	660.00 ✓
2 Dashboard assy	1	Tn 2,495.00	2,495.00 ✓
3 Steering air bag	1	Bure 1,450.00	1,450.00 ✓
4 Passenger air bag	1	✓ 1,450.00	1,450.00 ✓
5 Knee air bag	1	✓ 850.00	850.00 ✓
6 Airbag control unit	1	✓ 680.00	680.00 ✓
7 Airbag sensor	1	✓ 155.00	155.00 ✓
8 Front safety belt - RH / LH	2	Tn 560.00	1,120.00 ✓
9 Rear safety belt - RH / LH	2	Tn 350.00	700.00 ✓
10 Bonnet	1	Bz 1,200.00	1,200.00 ✓
11 Bonnet centre logo	1	✓ 58.00	58.00 ✓
12 Bonnet insulator	1	✓ 185.00	185.00 ? ✓
13 Bonnet insulator clips	10	✓ 6.50 30SN	65.00 ✓
14 Bonnet stopper - LH	1	✓ 12.00	12.00 X
15 Bonnet hinge - RH / LH	2	✓ 135.00	270.00 ? ✓
16 Bonnet absorber - RH / LH	2	✓ 90.00	180.00 ✓
17 Bonnet actuator - RH / LH	2	✓ 192.00	384.00 X
18 Bonnet spring - RH / LH	2	✓ 28.00	56.00 X
19 Bonnet center lock	1	Bz 68.00	68.00 ✓
20 Bonnet lock - LH	1	✓ 62.00	62.00 ?
21 Bonnet lock switch - LH	1	✓ 45.00	45.00 ?
22 Bonnet cable - front	1	✓ 58.00	58.00 ?
23 Bonnet cable - rear	1	✓ 48.00	48.00 ?
24 Support panel	1	Bu 585.00	585.00 ✓
25 Support panel top garnish	1	✓ 48.00	48.00 ?
26 Support panel top garnish clips	6	✓ 5.00 20SN	30.00 ✓
27 Support panel stricker	1	✓ 48.00	48.00 ✓
28 Brace panel	1	✓ 48.00	48.00 ?
29 Headlamp assy - RH / LH	2	Bz 2,580.00	5,160.00 ✓
30 Headlamp bracket - LH	1	✓ 65.00	65.00 ✓
31 Headlamp control unit - LH	1	✓ 520.00	520.00 ? ✓
32 Front grille	1	CM 128.00	128.00 ✓
33 Front grille beam	1	CM 185.00	185.00 ✓

18,213.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)

DATE : 26/07/2021

POLICY NO : 999995580

VEH REG NO : SLF357Y

MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)

CHASSIS NO : WDD2050422R213804

ENGINE NO : 27492030729390

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
34 Front grille beam moulding	3 A	78.00	234.00 444
35 Front grille centre logo	1	98.00	98.00 ✓
36 Front grille centre logo base	1	65.00	65.00 ✓
37 Front grille support	1	195.00	195.00 ✓
38 Front grille inner garnish	1	95.00	95.00 ✓
39 Front bumper	1	1,080.00	1,080.00 ✓
40 Front bumper reinforcement	1	350.00	350.00 ✓
41 Front bumper bracket - LH	1	230.00	230.00 ✓
42 Front bumper inner carrier - RH / LH	2	75.00	150.00 ✓
43 Front bumper strut - LH	1	42.00	42.00 ✓
44 Front bumper radar sensor	1	780.00	780.00 ✓
45 Front bumper sponge	1	125.00	125.00 ✓
46 Front bumper centre grille	1	108.00	108.00 ✓
47 Front bumper lower inner frame	1	105.00	105.00 ✓
48 Front bumper side retainer - LH	1	24.00	24.00 ✓
49 Front bumper sensor	5 4	138.00	690.00 828.00
50 Front bumper sensor seal	6	8.00	48.00 ✓
51 Front bumper sensor cable	1	130.00	130.00 ✓
52 Front bumper clips	15	5.50	82.50 50.00
53 Front bumper tow cover	1	35.00	35.00 ✓
54 Front bumper fog lamp cover - RH / LH	2	70.00	140.00 ✓
55 Front bumper fog lamp cover base - RH / LH	4 2	68.00	272.00 136.00
56 Front bumper lower chrome - centre	1	205.00	205.00 ✓
57 Front bumper lower chrome - RH / LH	2	152.00	304.00 ✓
58 Front bumper under cover	1	168.00	168.00 ✓
59 Front bumper lower spoiler	1	120.00	120.00 ✓
60 Front number plate garnish	1	98.00	98.00 ✓
61 Horn - RH / LH	2	135.00	270.00 ✓
62 Front fender - LH	1	555.00	555.00 ✓
63 Front fender inner shield (front) - RH / LH	2 1	92.00	184.00 ✓
64 Front fender inner shield clips - LH	20	6.50	130.00 ✓
65 Washer tank	1	98.00	98.00 ✓
66 Washer tank hose	1	53.00	53.00 ✓
67 Air-con condenser	1	950.00	950.00 ✓

7786



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)

DATE : 26/07/2021

POLICY NO : 999995580

VEH REG NO : SLF357Y

MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)

CHASSIS NO : WDD2050422R213804

ENGINE NO : 27492030729390

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
68 Radiator assy (inner)	1	750.00	750.00
69 Radiator assy (outer)	1	680.00	680.00
70 Radiator fan motor assy	1	1,050.00	1,050.00
71 Radiator top cover	1	55.00	55.00
72 Radiator lower cover	1	122.00	122.00
73 Air duct - RH / LH - missing torn	2	68.00	136.00
			32,786.50
		Add 10%	3,278.65
			36,065.15
SPECIAL NET			
74 ERP bracket	1	35.00	35.00
75 Front windscreen sealant	1	60.00	60.00
76 Radiator coolant (tin)	2	40.00	80.00
77 Power steering fluid (tin)	1	92.00	92.00
			267.00
LABOUR			
78 To remove and refit air-con condenser and refill air-con gas	1	150.00	150.00
79 To remove and refit radiator assy and pressure of air	1	100.00	100.00
80 To remove and refit dashboard, meter and grove box compartment to facilitates the repair	1	580.00	580.00
81 To remove and refit front windscreen glass	1	150.00	150.00
82 To dismantle and refit console box to enable replace airbag control unit	1	280.00	280.00
83 To remove and replace steering aigbag, passenger airbag, knee airbag. front and rear safety belt, airbag control unit and airbag sensor	1	800.00	800.00
84 To check and rectify wiring system	1	80.00	80.00
85 To panel beat and straighten both side front fender inner panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00
86 To putty and spray paint on affected areas	1	1,500.00	1,500.00
87 To re-program and reset all control module faulty code	1	580.00	580.00
			6,020.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

10% 28,290.00
21,829.00
31,119.00

2710



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 4

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)

DATE : 26/07/2021

POLICY NO : 999995580

VEH REG NO : SLF357Y

MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)

CHASSIS NO : WDD2050422R213804

ENGINE NO : 27492030729390

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 42,352.15
		ADD GST @ 7%	2,964.65
		GRAND TOTAL	<u>S\$ 45,316.80</u>

SINGAPORE DOLLAR FORTY-FIVE THOUSAND THREE HUNDRED SIXTEEN AND CENTS EIGHTY ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg
GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)
DATE : 04/08/2021
POLICY NO : 999995580
VEH REG NO : SLF357Y
MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)
CHASSIS NO : WDD2050422R213804
ENGINE NO : 27492030729390
REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Support panel bracket - RH / LH	2	168.00	336.00
2 Front bumper bracket - RH	1	230.00	230.00
3 Front bumper strut - RH	1	42.00	42.00
4 Horn brackets - RH / LH	2	45.00	90.00
5 Front fender - RH	1	555.00	555.00
6 Radiator top clips - RH / LH	2	12.00	24.00
7 Radiator vent line	1	85.00	85.00
8 Radiator vent line joint	1	112.00	112.00
9 Radiator lower support - RH	1	28.00	28.00
			1,502.00
		Add 10%	150.20
			1,652.20
TOTAL			S\$ 1,652.20
ADD GST @ 7%			115.65
GRAND TOTAL			S\$ 1,767.85

SINGAPORE DOLLAR ONE THOUSAND SEVEN HUNDRED SIXTY-SEVEN AND CENTS EIGHTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

Report Format :
Lump Sum / I.B.I. (\$)

☐ One Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)
TOTAL



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/07/2021

ESTIMATE

NO : QUOT202107-000065(00)

DATE : 26/07/2021

POLICY NO : 999995580

VEH REG NO : SLF357Y

MAKE/MODEL : MERCEDES BENZ C200 AMG
LINE (R18 LED)

CHASSIS NO : WDD2050422R213804

ENGINE NO : 27492030729390

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLF357Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Roof top moulding - LH <i>bent</i>	1	155.00	155.00 ✓
2 Front bumper top garnish <i>torn</i>	1	78.00	78.00 ✓
3 Front bumper pressure sensor <i>cracked</i>	1	165.00	165.00 ✓
4 Radiator top bearing -- LH <i>missing</i>	1	26.00	26.00 ✓
			424.00
		Add 10%	42.40
			466.40
		TOTAL	S\$ 466.40
		ADD GST @ 7%	32.65
		GRAND TOTAL	S\$ 499.05

SINGAPORE DOLLAR FOUR HUNDRED NINETY-NINE AND CENTS FIVE ONLY

Parts : \$31,119.00

SN : 318.00

Labour : 2,710.00

supp : 2,118.60

\$36,265.60

XS : 1,700.00

\$34,565.60

7% 2,419.59

\$36,985.19

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE