

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBQ 9099T

at Workshop m/s: Evoform

of _____

Insured: SHA 351 L

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$11k.

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

PTVA

Date: _____ Person Contacted: JTA R 3193 Vehicle: IN / OUT

Veh No: FBQ9099T Yr Regn: 31/12/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB160R c.c. 149

Colour: Red / Black A/C: Insured / Std / NI / NA

Sp.Reading: 14933 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MJHKC2889K513843F

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110 / 70 R17

R: 150 / 60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 17/7/21 D.O.I. 27/7/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>31/7/21</u>	<u>4/5 @ 1700 confirmed w.r. MR Teo.</u>

Date/Time, File Pass to?

: Preli. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1)

2)

Add Fee: : Site Insp (\$) _____ S + RS, SI

: Interview (\$) Photos

: Tech. Invs (\$) Others

: Weekend (\$)

Report Format: _____

Lump Sum / I.B.I.: (\$) _____

TOTAL

EROFIA MOTOR TRADING PTE LTD

AXIA

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

E-mail: erofia@singnet.com.sg

Name : Chua Yeow Leng

Accident Date : 17-Jul-21

Vehicle No : FBQ9099T

Vehicle Model : Honda
CB150R

Estimated Repair Costs

Qty	Description	Amount S(\$)
List Items		
1	Front fender <i>2</i>	\$ 175.00 <i>x</i>
2	Front fork assy- L/R/H <i>see</i>	\$ 960.00 <i>x</i>
1	Front fork under bracket <i>11</i>	\$ 255.00 <i>x</i>
1	Front wheel rim <i>see</i>	\$ 850.00 <i>x</i>
1	Front rim shaft <i>see</i>	\$ 68.00 <i>✓</i>
1	Front rim bearing <i>11</i>	\$ 48.00 <i>x</i>
1	Front brake disc <i>11</i>	\$ 385.00 <i>x</i>
1	Handle-bar <i>sent</i>	\$ 155.00 <i>?</i>
2	Handle-bar ends <i>o/s Daged</i>	<i>35</i> \$ 90.00 <i>ipc</i>
1	Hand grips (1-set) <i>Toin</i>	<i>60</i> \$ 80.00 <i>✓</i>
1	Brake lever <i>see</i>	<i>45</i> \$ 65.00 <i>✓</i>
1	Front signals (1-set) <i>o/s one</i>	<i>120</i> \$ 230.00 <i>✓</i>
1	Mirrors (1-set) <i>o/s cur</i>	<i>90</i> \$ 190.00 <i>✓</i>
1	Trottle cable <i>cur</i>	\$ 145.00 <i>✓</i>
1	Front footrest - R/H <i>300</i>	<i>60</i> \$ 95.00 <i>✓</i>
1	Front footrest bracket - R/H <i>sent</i>	\$ 245.00 <i>✓</i>
1	Front lower side cover - R/H <i>cur</i>	<i>120</i> \$ 165.00 <i>✓</i>
1	Crash bar <i>cur</i>	\$ 265.00 <i>✓</i>
		\$ 4,466.00
		Less 10% \$ 446.60
		\$ 4,019.40
 Special Net Items		
1	Number plate (1 set) <i>ft see</i>	\$ 38.00 <i>10</i>
2	Fork oils <i>11</i>	\$ 30.00 <i>x</i>
2	Fork oil seals <i>11</i>	\$ 56.00 <i>x</i>
1	Steering cone (1 set) <i>11</i>	\$ 95.00 <i>x</i>
1	Rear box <i>cur</i>	\$ 420.00 <i>250</i>
1	Rear box bracket <i>sent</i>	\$ 180.00 <i>✓</i>
		\$ 819.00

*Not Ad head
27/7/21*

*2/s \$1700
who photo after repair
3 days.*

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

E-mail: erofia@singnet.com.sg

Name : Chua Yeow Leng

Accident Date : 17-Jul-21

Vehicle No : FBQ9099T

Vehicle Model : Honda
CB150R

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service	\$ 30.00 ✓
2	To check wiring and reset headlamp focusing	\$ 11 80.00 X
3	To respray paint	\$ 350.00 / 50
4	To repair body frame	\$ 11 380.00 X
5	To provide labour	\$ 420.00 250
		<hr/>
		\$ 1,260.00
		<hr/>
	Grand Total	\$ 6,098.40

Singapore Dollars: Six Thousand Ninety-Eight and Cents: Forty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P. 1408
102
1207.2