



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: JEREMY GOH			Ref: CS3/AIG21004802/T1tf3e2-1 Date: 29/07/2021 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLU 8377H	Veh. Inspected	SFM 8121S	
Policy No.	1900253224	Coverage (\$)	0.00	
Claim No.	8732564805SG	Excess (\$)	0.00	
Assign From	JEREMY GOH	Assign Date	27/07/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HARRIER	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600063257	Colour	BLACK	
Odometer	102428 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	PIRELLI	6 mm	
L/H Front Tyre	235/55 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/55 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/55 R18	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/04/2021	Inspection Date	20/04/2021	
Survey held at	PAUL HOE BATTERIES & MOTOR SERVICES BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	