

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5309L*Not Authenical
Penny B4 paint***AAD2107-****65796-13**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

26 JUL 2021**SHD5309L**

JTDKB3FU903076748

TOYOTA

PRIUS

23/07/2021

TOKIO

15/11/2018

PART**LIST**

1	PANEL SUB-ASSY, BACK DOOR	\$	Bu	1,147.80	✓
1	SPOILER SUB-ASSY, REAR	\$	Sn	1,575.40	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	CM	925.60	✓
1	STAY ASSY, BACK DOOR, LH	\$	Sn	242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	Sn	242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	R	61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	R	61.00	X
1	WEATHERSTRIP, BACK DOOR	\$	Sn	372.30	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	R	54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	R	54.60	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	R	47.90	✓
1	COVER, BACK DOOR TRIM	\$	Sn	24.90	X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	miy	241.90	✓
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	Sn	175.10	X
1	COVER, REAR FLOOR (CTR)	\$	Sn	229.90	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	Bu	650.30	✓
1	LENS AND BODY, REAR LAMP, RH	\$	Sn	502.00	X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	CM	451.80	✓
1	PANEL SUB-ASSY, QUARTER, RH	\$	R	871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	Sn	139.80	X
1	COVER, REAR BUMPER	\$	Bu	442.60	✓
1	COVER, REAR BUMPER, LOWER	\$	miy	15.40	✓
1	FILLER, REAR BUMPER EXTENSION, RH	\$	Sn	123.70	X
1	GUARD, REAR BUMPER, CENTER	\$	Bu	576.30	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	Bu	332.70	✓
TOTAL		\$		9,563.10	
25%		\$		2,390.78	
		\$		7,172.33	

AAD2107-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5309L

Special Nett

1SET PARKING AID	\$	Ref	700.00	2000
1 REAR SPOILER CLIP	\$	na	60.00	X
1 REAR BUMPER CLIP	\$	na	65.00	5000
1 REAR FENDER CLIP	\$	na	66.00	X
1 REAR TAIL LAMP CLIP	\$	na	65.00	X
1 END PANEL INNER TRIM CLIP	\$	na	60.00	X
1 CLIP(FOR REAR DOOR TRIM BOARD)	\$	na	65.00	X
1 BOOT STICKER TRANSCAB	\$	na	100.00	3000
1 BOOT STICKER TEL.NO	\$	na	100.00	3000
2 WINDSCREEN SEALANT	\$	na	150.00	4000
1 WINDSCREEN MOULDING	\$	na	200.00	✓
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	3000
TOTAL	\$		1,001.00	1761

TOTAL PARTS	\$	8,543.40
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	300
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	880
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	600
To Check Electrical Lighting Concerned.	\$	170.00	200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	5000
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	na	170.00 X
TOTAL	\$	4,790.00	

13,723.33