

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5309L*Not Authenical
Recovery B4 paint***AAD2107-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

26 JUL 2021**SHD5309L****JTDKB3FU903076748****TOYOTA****PRIUS****23/07/2021****TOKIO****15/11/2018****PART****LIST**

1	PANEL SUB-ASSY, BACK DOOR	\$	Bu	1,147.80	✓
1	SPOILER SUB-ASSY, REAR	\$	Ln	1,575.40	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	CM	925.60	✓
1	STAY ASSY, BACK DOOR, LH	\$	Ln	242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	Ln	242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	R	61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	R	61.00	X
1	WEATHERSTRIP, BACK DOOR	\$	Ln	372.30	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	Ln	54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	Ln	54.60	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	Ln	47.90	✓
1	COVER, BACK DOOR TRIM	\$	Ln	24.90	X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	my	241.90	✓
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	Ln	175.10	X
1	COVER, REAR FLOOR (CTR)	\$	Ln	229.90	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$		650.30	?
1	LENS AND BODY, REAR LAMP, RH	\$	Ln	502.00	X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	CM	451.80	✓
1	PANEL SUB-ASSY, QUARTER, RH	\$	R	871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	Ln	139.80	X
1	COVER, REAR BUMPER	\$	R	442.60	✓
1	COVER, REAR BUMPER, LOWER	\$	my	15.40	✓
1	FILLER, REAR BUMPER EXTENSION, RH	\$		123.70	?
1	GUARD, REAR BUMPER, CENTER	\$	R	576.30	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	R	332.70	✓
TOTAL		\$		9,563.10	
25%		\$		2,390.78	
		\$		7,172.33	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5309L

AAD2107-

Special Nett

1SET PARKING AID	\$	Red	700.00	2000
1 REAR SPOILER CLIP	\$	na	60.00	X
1 REAR BUMPER CLIP	\$	na	65.00	5000
1 REAR FENDER CLIP	\$	na	66.00	X
1 REAR TAIL LAMP CLIP	\$	na	65.00	X
1 END PANEL INNER TRIM CLIP	\$	na	60.00	X
1 CLIP(FOR REAR DOOR TRIM BOARD)	\$	na	65.00	X
1 BOOT STICKER TRANSCAB	\$	na	100.00	3000
1 BOOT STICKER TEL.NO	\$	na	100.00	3000
2 WINDSCREEN SEALANT	\$	na	150.00	4000
1 WINDSCREEN MOULDING	\$	na	200.00	✓
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	3000
TOTAL	\$		1,001.00	
TOTAL PARTS	\$		8,543.40	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	300
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	880
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	600
To Check Electrical Lighting Concerned.	\$		170.00	200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,800.00	5000
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	na	170.00	X
TOTAL	\$		4,790.00	

Trans-cab Auto Services Pte Ltd

AAD2107-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5309L

Over All Total \$ 20,505.73

(PART-BY-PART) Repair Days

~~10 Days~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: