

(08/11/13) wef

ASS. REC. BY: marcus

REF:


CC6/AIG21007957/urs3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SYM 1517H
at Workshop m/s: Zan Lem
of _____
Insured: SKW 4087Y
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 816k.
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 2 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 863D Vehicle: IN / OUT

Veh No: SYM 1517H Yr Regn: 22/12/08
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA /
Make: Honda Fit c.c. 1339
Colour: Purple A/C: Insured / Std / NI / NA
Sp. Reading: 177873 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: GE 61122764
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/60 R14
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>23/7/21</u>		D.O.I. <u>27/7/21</u>	

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

coe until 21-12-2023 LTA \$6635

29/7/21 L/S \$1300 confirmed with willian

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

TOTAL



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SKW4087Y

Date of Accident : 23 July 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Yian Huei Chin

Date : 24 July 2021

Estimate To Repair SJM1517H - Honda FIT 1.3G A

Chassis No : GE61122764

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid lock top 11	\$ 242.30
02	1 pc	tailgate lid weatherstrip 11	\$ 129.20
03	1 pc	tailgate lid Fit badge 11	\$ 29.10
04	1 pc	rear bumper spare Dis	\$ 936.70
05	1 pc	rear bumper tow hook cover 11	\$ 28.80
06	1 pc	rear bumper side retainer right 11	\$ 16.20
07	8 ps	rear bumper fastener clips @ \$4.50 11	\$ 36.00
08	2 ps	rear bumper top bracket @ \$9.80 11	\$ 19.60
09	2 ps	rear bumper end splashshield cover @ \$25.80 11	\$ 51.60
10	1 pc	rear end panel 11	\$ 480.00
11	1 pc	rear end panel inner trim 11	\$ 183.90
12	4 ps	rear end panel inner trim clips @ \$4.50 11	\$ 18.00
13	1 pc	rear lamp o/s 11	\$ 390.70
14	1 pc	rear lamp panel o/s 11	\$ 125.00
Less 20 %			\$ 2,687.10
			\$ 537.42
			\$ 2,149.68
<u>SPECIAL NETT ITEMS</u>			
15	1 set	rear bumper parking sensor 11	\$ 280.00
			\$ 280.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 50.00
02		To rust-proofing of the affected areas.	\$ 11 60.00
03		To reinstall of rear bumper parking sensor.	\$ 80.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00
05		Putty and spray painting of the affected portion.	\$ 750.00
			\$ 1,640.00
Total			\$ 4,069.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

req. 17/07/2021 C995h
Marcus L64

2 988.5
202
791.12
1657.12
1320