



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKK6335G

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No 51218
Reg No/Reg Date SKK6335G / 16/06/2021
Date In/Mileage
Chassis No SKK6335G
Engine No 25693030309060
Make/Model MB/S 450 4MATIC SEDAN LONG
Colour/Trim 029 998 Anthracite / 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator			
WI000576	Credit	26/07/2021/ 15:37	AQ	305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN POLICY NO/ACC DATE : 21005811 / 24/07/2021 DRIVE IN 26-07-2021 // TP CAR NO: SLM4404G (INDIA INTERNATIONAL INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :					
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT					480.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT					120.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.					1440.00
A BPIRES RESPRAY REAR BUMPER					600 720.00
M REAR BUMPER	1.00	2083.13	00.00		2083.13
M REAR BOTTOM PANEL	1.00	684.67	00.00		684.67
M RH/R BOTTOM PANEL CHROME	1.00	213.36	00.00		213.36
M LH/R BOTTOM PANEL CHROME	1.00	213.36	00.00		213.36
M CT/R BOTTOM PANEL TRIM	1.00	250.81	00.00		250.81
M CT/R BOTTOM PANEL CHROME	1.00	481.11	00.00		481.11
M RH/R BASIC MOUNTING FOR BUMPER	1.00	144.63	00.00		144.63
M RH/R BUMPER GARNISH	1.00	112.27	00.00		112.27
M LH/R BUMPER GARNISH	1.00	112.27	00.00		112.27
M RH/R EXHAUST TAIL PIPE TRIM	1.00	325.10	00.00		325.10
M RH/R EXHAUST TAIL PIPE BRACKET	1.00	64.27	00.00		64.27
M RH/R TAIL LAMP	1.00	796.62	00.00		796.62

LK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
BIB: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 8,241.60
7% GST on 8241.60 576.91
Total Payable 8,818.51

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany