

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6047 R

1 pc	Lamp Assy- Rear fog	\$	201.50	X <i>one</i>
1 pc	Rear bumper	\$	459.40	X <i>Rx</i>
1 pc	Rear bumper reinforcement	\$	294.80	X <i>7</i>
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket	\$	20.00	X <i>u</i>
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00	X <i>u</i>
2 pcs	Rear bumper n/s & o/s stay	\$	276.20	X <i>u</i>
2 pcs	Rear bumper n/s & o/s side bracket	\$	66.20	X <i>u</i>
1 pc	Rear bumper lower moulding centre	\$	216.50	X <i>de</i>
1 pc	Rear bumper lower cover	\$	47.50	X <i>cut</i>
1 pc	Rear bumper cap hook	\$	9.10	X <i>u</i>
2 pcs	Rear bumper n/s & o/s reflector @ \$31.90	\$	63.80	X <i>u</i>
		\$	1,670.00	<i>465.50</i>
		\$	334.00	
		\$	1,336.00	<i>372.40</i>

Less 20%

JKK Auto Consultants hence notify

1 set	Rear bumper clips
1 set	Reverse sensor
1 pc	Rear number plate with casing

To check wiring

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc

To putty and spray painting on rear bumper, end panel, rear bumper lower cover

To apply rustproofing on the repaired and replaced panels.

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

372.40	\$	180.00	x un
45			
430		200	
<hr/>	\$	750.00	
\$847.40			200
2 days	\$	600.00	
#	\$	120.00	x un
MIC	<hr/>	<hr/>	
	\$	3,584.00	

195/65K15

Tamplin 97445749
wp' 27/7/21 @ 330pm

2 days
p/p Requiring new pants

For Mr. D. H. H. H. H.