

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Jul-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6047 R

1 pc	Lamp Assy- Rear fog	\$	201.50 X
1 pc	Rear bumper	\$	459.40 R
1 pc	Rear bumper reinforcement	\$	294.80 ?
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket	\$	20.00 X
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00 X
2 pcs	Rear bumper n/s & o/s stay	\$	276.20 X
2 pcs	Rear bumper n/s & o/s side bracket	\$	66.20 X
1 pc	Rear bumper lower moulding centre	\$	216.50 de
1 pc	Rear bumper lower cover	\$	47.50 cut
1 pc	Rear bumper cap hook	\$	9.10 X
2 pcs	Rear bumper n/s & o/s reflector @ \$31.90	\$	63.80 X
		\$	1,670.00
		Less 20%	\$ 334.00
			\$ 1,336.00

S/Nett

1 set	Rear bumper clips	\$	48.00 30?
1 set	Reverse sensor	\$	280.00 200?
1 pc	Rear number plate with casing	\$	45 50.00 cur
Sundry		\$	50.00 X
To check wiring		\$	50.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc		\$	750.00 200
To putty and spray painting on rear bumper, end panel, rear bumper lower cover		\$	600.00 200
To apply rustproofing on the repaired and replaced panels.		\$	120.00 X
		\$	3,584.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MIC

195/65K15

Tanpin 97445749

wp' 27/7/21 @ 330pm

2 days

p/p Resurvey new parts

Tanpin @ 16kmph. w.m.