



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007971/R1uf3e2	
			Date: 12/10/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6139D	Veh. Inspected	SLL 8977Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/07/21/2054	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	27/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS 1.5E CVT	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MHFB29F3X02007250	Colour	GREY
	Odometer	324219 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	DUNLOP	5 mm
	L/H Front Tyre	195/50 R16	DUNLOP	5 mm
	R/H Rear Tyre	195/50 R16	DUNLOP	5 mm
	L/H Rear Tyre	195/50 R16	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/07/2021	Inspection Date	27/07/2021
	Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	