

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 27.07.21INSURANCE: AIG ASIAMODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHD8622L

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Smart Key Antenna	1		\$40.50
	Rear Bumper	1		\$459.40
	Rear Bumper Reinforcement	1		\$394.80
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20
	Rear Bumper Centre Moulding Assy	1		\$451.25
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00
	Rear Bumper Cover Clips	10	\$2.20	\$22.00
	Rear Bumper Fog Lamp	1		\$201.50
	Rear Bumper Towing Cover	1		\$98.80
	SUB TOTAL			\$2,099.45
	LESS 20%			\$419.89
	DISCOUNTED TOTAL			\$1,679.56
	Rear Bumper Mat	1		\$50.00
	Rear Bumper Reverse Sensor	1		\$180.00
	Rear No.Plake W/Trim Cover	1		\$55.00
	S/NETT TOTAL			\$285.00
	SPARE PARTS TOTAL			\$1,964.56
	Labour Charge			
	Panel Beating			\$400.00
	Spray Painting Charge			\$300.00
	Remove/Refix Reverse Sensor			\$120.00
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$2,784.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran LHK w/p
 27/6/21 16/5
 82235769
 theran@LHK auto. ion
 2 days

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: