

SLJ2646D
TP/CHINA**REPAIR DETAILS****Reference**

Part Source: (Last Synchronised: 03 Aug 2021)
 Parts: N/A HONDA SHUTTLE 1.5 G (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLJ2646D)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*570.00 F
2	1		*1 PC REAR BUMPER LOWER SKIRT	0.00	0.00	*380.00 F
3	1		*6 PCS REAR BUMPER CLIPS @2/PC	0.00	0.00	*12.00 F
4	1		*1 PC TAILGATE EMBLEM (SHUTTLE)	0.00	0.00	*45.00 F
Total Parts (S\$)						1,007.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 SET REVERSE SENSOR	200.00
Sub Total (S\$)			200.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX REAR BUMPER ASSY, LOWER SKIRT, REAR REFLECTORS, TO KNOCK & REPAIR TAILGATE, REAR PANEL & REALIGN THE SAME	New	500.00
2	PUTTY & RESPRAY REAR BUMPER, BEAM, REAR LOWER SKIRT, TAILGATE & REAR AFFECTED AREAS	New	700.00
Gross Labour Cost (S\$)			1,200.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Not Notarised
 11 Sep @ 1800h
 Resurvey After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRepairer&fuseaction=...> 03/08/2021