



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2108472

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/12/2021
Reference CC3/CTI21007991/Krs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5377P
Insured Veh. SFS 301K
Claim No. SNM21D204196/LKKDS
Policy No. DMPCSNW00073862103
Accident Date 10/07/2021
Inspection Date 26/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21007991/Krs3q2	
			Date: 09/12/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFS 301K	Veh. Inspected	SHD 5377P	
Policy No.	DMPCSNW00073862103	Coverage (\$)	0.00	
Claim No.	SNM21D204196/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	26/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDKB3FU503078562	Colour	M . P. WHITE / RED	
Odometer	196476 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	9 mm	
L/H Front Tyre	195/65 R15	SAILUN	9 mm	
R/H Rear Tyre	195/65 R15	SAILUN	4 mm	
L/H Rear Tyre	195/65 R15	SAILUN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/07/2021	Inspection Date	26/07/2021	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5377P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL SUB -ASSY ,FRONT DOOR ,LH	TO REPAIR SEE LABOUR	1,300.70	-
1	FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE ,LH	SERVICEABLE	193.50	-
1	HANDLE ASSY ,FRONT DOOR OUTSIDE ,LH	SERVICEABLE	390.60	-
1	WEATHERSTRIP FRONT DOOR LH	SERVICEABLE	231.30	-
1	HINGE ASSY ,FRONT DOOR ,LOWER LH	TO REPAIR SEE LABOUR	110.60	-
1	HINGE ASSY ,FRONT DOOR ,UPPER LH	TO REPAIR SEE LABOUR	97.50	-
1	TAPE ,BLACK OUT ,NO.1 FRT LH	NOT NECESSARY	13.30	-
1	TAPE ,BLACK OUT ,NO.2 FRT LH	NOT NECESSARY	43.50	-
1	TAPE ,BLACK OUT ,NO.3 FRT LH	NOT NECESSARY	26.30	-
1	MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH	SERVICEABLE	926.00	-
1	REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH	SERVICEABLE	238.30	-
1	PANEL SUB-ASSY ,REAR DOOR ,LH	TO REPAIR SEE LABOUR	1,294.90	-
1	HINGES ASSY ,REAR DOOR LOWER LH	TO REPAIR SEE LABOUR	87.10	-
1	HINGES ASSY ,REAR DOOR UPPER LH	TO REPAIR SEE LABOUR	98.90	-
1	TAPE ,BLACK OUT ,NO.1 REAR LH	NOT NECESSARY	21.90	-
1	TAPE ,BLACK OUT ,NO.2 REAR LH	NOT NECESSARY	34.90	-
1	TAPE ,BLACK OUT ,NO.3 REAR LH	NOT NECESSARY	15.40	-
1	MOTOR ASSY ,POWER WINDOW REGULATOR ,REAR LH	SERVICEABLE	926.00	-
1	REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,LH	SERVICEABLE	206.70	-
1	MOULDING ASSY ,BODY ROCKER PANEL LH	TO REPAIR SEE LABOUR	594.80	-
	LESS 25% DISCOUNT		-1,713.05	-
			5,139.15	-
	<u>SPECIAL NETT ITEMS</u>			
1	FENDER CLIP (SN)	NOT NECESSARY	65.00	-
1	FENDER LINER CLIP (SN)	NOT NECESSARY	65.00	-
1	SET DOOR WEATHERSTRIP CLIP (SN)	NOT NECESSARY	65.00	-

Report Ref No. CC3/CTI21007991/Krs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT DOOR STICKER TRANSCAB (SN)	NECESSARY	100.00	60.00
1	REAR DOOR STICKER TEL NO (SN)	NECESSARY	100.00	60.00
1	TYRE (SN)	SERVICEABLE	350.00	-
1	RIM (SN)	SERVICEABLE	1,879.40	-
1	RIM COVER (SN)	SERVICEABLE	400.00	-
1	SET CLIP ,ROCKER PANEL MOULDING (SN)	NOT NECESSARY	65.00	-
			3,089.40	120.00
	LABOUR			
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB -ASSY ,FRONT DOOR ,LH ,HINGE ASSY ,FRONT DOOR ,LOWER LH,HINGE ASSY ,FRONT DOOR ,UPPER LH,PANEL SUB-ASSY ,REAR DOOR ,LH,HINGES ASSY ,REAR DOOR LOWER LH,HINGES ASSY ,REAR DOOR UPPER LH AND MOULDING ASSY ,BODY ROCKER PANEL LH .		1,400.00	300.00
	PUTYY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,400.00	660.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .	NOT NECESSARY	240.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
			3,590.00	960.00
GRAND TOTAL			11,818.55	1,080.00
RECOMMENDED COST OF REPAIRS				1,080.00

Report Ref No. CC3/CTI21007991/Krs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5377P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

