

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5377P*Not With in
Return 134 paint***AAD2107-***810806*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

26 JUL 2021**SHD5377P****JTDKB3FU503078562****TOYOTA****PRIUS****10/07/2021***China***19/12/2018**

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	<i>n</i> 1,300.70 <i>X</i>
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	<i>sn</i> 193.50 <i>X</i>
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	<i>sn</i> 390.60 <i>X</i>
1	WEATHERSTRIP, FRONT DOOR, LH	\$	<i>sn</i> 231.30 <i>X</i>
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	<i>n</i> 110.60 <i>X</i>
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	<i>n</i> 97.50 <i>X</i>
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	<i>nn</i> 13.30 <i>X</i>
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	<i>nn</i> 43.50 <i>X</i>
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	<i>nn</i> 26.30 <i>X</i>
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	<i>sn</i> 926.00 <i>X</i>
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	<i>sn</i> 238.30 <i>X</i>
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	<i>n</i> 1,294.90 <i>X</i>
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	<i>n</i> 87.10 <i>X</i>
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	<i>n</i> 98.90 <i>X</i>
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	<i>nn</i> 21.90 <i>X</i>
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	<i>nn</i> 34.90 <i>X</i>
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	<i>nn</i> 15.40 <i>X</i>
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH	\$	<i>sn</i> 926.00 <i>X</i>
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	<i>sn</i> 206.70 <i>X</i>
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	<i>n</i> 594.80 <i>X</i>
TOTAL		\$	6,852.20
25%		\$	1,713.05
		\$	5,139.15

Special Nett

1 FENDER CLIP

\$ *nn* 65.00 *X*

Trans-cab Auto Services Pte Ltd

AAD2107-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5377P

1 FENDER LINDER CLIP	\$	nn	65.00	X
1SET DOOR WEATHERSTRIP CLIP	\$	nn	65.00	X
1 FRT DOOR STICKER TRANSCAB	\$	nn	100.00	Gorn
1 REAR DOOR STICKER TEL. NO	\$	nn	100.00	Gorn
1 TYRE	\$	nn	350.00	X
1 RIM	\$	nn	1,879.40	X
1 RIM COVER	\$	nn	400.00	X
1SET CLIP, ROCKER PANEL MOULDING	\$	nn	65.00	X
TOTAL	\$		3,089.40	
TOTAL PARTS	\$		8,228.55	

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 300l

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 660l

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ nn 240.00 X

To Check Electrical Lighting Concerned.

\$ nn 170.00 X

TOTAL \$ 3,590.00**Over All Total \$ 11,818.55****(PART-BY-PART) Repair Days**

20 days

2 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: