

190848

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

HP 96699986

INVOICE

Mr. Mohammad Khidir Bin Kassim
Apt Blk146 Bukit Batok
Avenue 6 #02-357
Singapore 650146

Invoice No : PA/19090001/tpw
Our Ref : PA/FBH6966/0819/tpw
Date : 06 September 2019

Claim Type	Third Party	Date of Accident	: 05 August 2019
Vehicle No.	FBH 6966 H	Date of Inspection	: 19 August 2019
No	Description		Amount (S\$)
1	Survey fees inclusive of Transportation and Photographs (40) copies		\$350.00
		Total	\$350.00
Singapore Dollar: Three Hundred And Fifty Only			
All payments made payable to : Prudent Adjustors Services			


Prudent Adjustors Services

PRUDENT ADJUSTORS SERVICES
BLOCK 807 ELIAS ROAD #05-192
SINGAPORE (510607)
BUSINESS REGN. No. 53193457L

VEHICLE APPRAISAL REPORT

Mr. Mohammad Khidir Bin Kassim
Apt Blk146 Bukit Batok
Avenue 6 #02-357
Singapore 650146

Our Ref : PA/FBH6966/0819/tpw
Date : 06 September 2019

REFERENCE PARTICULARS

Your Reference No : Not Advised
Date of Accident : 05 August 2019

Date of Assignment : 19 August 2019
Date of Inspection : 19 August 2019
Date of Re-inspn. : N.A.

PARTICULARS OF VEHICLE

Regn. No : FBH 6966 H
Make : Piaggio
Model : Vespa GTS Super/Supersport 300
Year : July 2018 (COE Exp: July 2028)

Odometer : No Key
Color : Grey
Chassis No. : Blocked
Engine No : MA33M1008224

TYRE / CONDITION

<u>Location</u>	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Michelin	120/70 R12	4 mm
Rear	Michelin	130/70 R12	5 mm

DAMAGE PROFILE

The Scooters sustained severe damage at all sides. Chassis frame badly distorted and damaged beyond repair. The Scooters was not able to restore to road worthy condition.

ASSESSMENT SUMMARY


The Scooters was rendered not safe to repair. **Hence recommended as Total Loss.**


Market value of the Scooter at time of loss was approximately \$18,500.00
LTA rebate as on 19/08/2019 was \$4,951.00. Nett value was \$13,549.00 approximately.
No wreck offer by repairer nor any salvage value
Except LTA rebate at deregistration.

Survey conducted at: United Cycles LLP

Enclosed (40) photographs depicting damage to the vehicle.
The survey was conducted on a **WITHOUT PREJUDICE BASIS.**


Prudent Adjustors Services
Bok Jee Tan





PRUDENT ADVISORY

PRUDENT ADVISORY




PRUDENT ADVISORY

PRUDENT ADVISORY










PRUDENT ADVISORY

PRUDENT ADVISORY













PRUDENTIAL
INSURANCE



PRUDENTIAL
INSURANCE



