



Your Ref : DP.sa.11515.21.FCI

Date: 22nd Sep 2021

Our Ref : CS/LAW21007999/T1qf3e2

M/s Daniel Poon & Co.

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBH 6966H
INSURED VEHICLE: SHC 656Y
ACCIDENT ON 05/08/2019**

Instruction was received to inspect the vehicle Reg. No. FBH 6966H. The inspection was conducted on 03/08/2021 at the premises of M/s 25 Kaki Bukit Rd 4 #01-25 Synergy, Repairer: United Cycles LLP.

The following vehicle information was recorded:

Registration Number	: FBH 6966H
Make/Model	: Vespa GTS Super / Supersport 300
Year of Registration	: 2018
Body Colour	: Grey
Chassis Number	: ZAPMA330000008073
Engine Capacity	: 278 cc

The vehicle sustained damages at the front portion and n/s body. The chassis frame and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 15,300.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 4,952.00)
Nett Liability	<u>S\$ 10,348.00</u> =====

Vehicle Inspected By:



MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.