



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0603/2021/KS
DATE : 27-Jul-21
WIP : 35597

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/7/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ONG MUN WAI EUGENE
ADDRESS : 2 JALAN TELANG
SINGAPORE 576673
TELEPHONE : HP +65 94389697
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100401461-06
VEHICLE NO : **SKR 3500 D**
MODEL CODE : AUDI A6 C7 2.0 TFSI MU
MODEL YEAR : 30/1/2015
ENGINE NO : CDN 408232
CHASSIS NO : WAUZZZ4G1EN137822
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Jul-21
PLACE OF ACCIDENT : 374 CLEMENTI AVE 4, SINGAPORE 120374

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 3500 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS , HORNS , OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING ATD	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00 1000	
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET. ✓	\$ 3,000.00 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>6,872.00</u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 3500 D

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>del d</i>	1	\$ 2,832.00	✓
2	FRONT BUMPER FIXING PARTS <i>neu</i>	1	\$ 276.00	X
3	FRONT BUMPER SECURING STRIP <i>neu</i>	1	\$ 14.00	X
4	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 190.00	?
5	FRONT BUMPER COVER TRIM - CENTER ?	1	\$ 99.00	?
6	FRONT BUMPER END CAP <i>neu</i>	1	\$ 143.00	X
7	FRONT BUMPER GRILE - RH <i>neu</i>	1	\$ 153.00	X
8	RADIATOR GRILLE <i>cruld</i>	1	\$ 1,332.00	✓
9	RADIATOR GRILLE STRIKER PLATE ?	1	\$ 36.00	?
10	FOAM FILLER PIECE ?	1	\$ 99.00	?
11	FRONT REINFORCEMENT BEAM <i>neu</i>	1	\$ 872.00	X
12	FRONT BUMPER TOP COVER <i>cruld</i>	1	\$ 123.00	✓
13	FRONT BUMPER GUIDE PIECE - RH <i>neu</i> ?	1	\$ 38.00	?
14	FRONT BUMPER BRACE - RH ?	1	\$ 30.00	?
15	"CAUTION" STICKER <i>neu</i>	1	\$ 14.00	✓
16	"A/C" STICKER	1	\$ 30.00	✓
17	HORN - RH <i>neu</i>	1	\$ 286.00	X
18	HORN BRACKET - RH <i>neu</i>	1	\$ 43.00	X
19	FRONT PARKING AID SENSOR <i>neu</i>	1	TBC	X
20	FRONT PARKING AID SEAL RING <i>neu</i>	1	\$ 6.00	X
SUB TOTAL SPARE PARTS			\$ 6,616.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 3500 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET <i>Dented</i>	1	\$ 5,436.00	✓
22	BONNET ATTACHMENT PARTS <i>Alu</i>	1	\$ 144.00	+
23	BONNET HINGE - LH / RH <i>2</i>	1	\$ 161.00	x
24	BONNET CATCH HOOK <i>1</i>	1	\$ 140.00	x
25	BONNET LOCK BAR <i>2</i>	2	\$ 100.00	x
26	BONNET LOCK WITH MICRO SWITCH <i>2</i>	2	\$ 427.00	+
27	BONNET BOWDEN CABLE <i>1</i>	1	\$ 58.00	+
28	HEADLIGHT MOUNTING - LH / RH <i>?</i>	1	\$ 118.00	?
29	HEADLIGHT - RH <i>cracked</i>	1	\$ 3,321.00	✓
30	HEADLIGHT LIFT CYLINDER - RH <i>1</i>	1	\$ 236.00	x
31	HEADLIGHT HOSE - RH <i>2</i>	1	\$ 191.00	x
32	HEADLIGHT WASHER CAP - RH <i>1</i>	1	\$ 58.00	✓
33	RADIATOR AIR GUIDE - LH / RH <i>1</i>	1	\$ 64.00	✓
34	RADIATOR COVER - UPPER CENTRE <i>?</i>	1	\$ 29.00	✓
35	FRONT NO PLATE <i>dented</i>	S/N	\$ 60.00	✓
36	SUNDRIES <i>?</i>	1	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 17,459.00	
TOTAL LABOUR CHARGES		:	\$ 6,872.00	
GRAND TOTAL		:	\$ 24,331.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL/22/07/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian L
27/07/21

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT