

Certification for Bus Repairs



CBR REF NO. : HG20213149

Depot : HG

Report No.: W28762021

BUS VEHICLE NO. : SG5320G

Driver's Co no. & Name : 81483 Ye Qingguang

Accident Date : 26/06/2021

Date in : 26/06/2021

Date Out : 28/06/2021

Yr Of Reg	Make / Model	Chassis No.
2016	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P923GA176475

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30730009	BOSTICK SEALANT 7008	1	\$15.00
30750142	REAR ENGINE COMPARTMENT DOOR	1	\$3,104.00
42311205	PLATE;2MX1M;SOUND ABSORBER	1	\$463.00
TOTAL FOR PARTS			S\$ 3582.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	184.00
2	Contractor's repair charges	S\$	300.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 484.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 4066.00

Certification for Bus Repairs



CBR REF NO. : HG20213149

Depot : HG

Report No.: W28762021

BUS VEHICLE NO. : SG5320G

Driver's Co no. & Name : 81483 Ye Qingguang

Accident Date : 26/06/2021

Date in : 26/06/2021

Date Out : 28/06/2021

Yr Of Reg	Make / Model	Chassis No.
2016	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P923GA176475
TOTAL DAMAGE		S\$ 4066.00
Overheads		S\$ 1219.80
Towing Charges		S\$ -
Repair Period : 1 day(s)	Loss of Use	S\$ 416.80
TOTAL LOSS		S\$ 5702.60

Prepared By : Zakaria Bin Ahmad

Date : 25/07/2021

Approved By
Workshop Mgr : Aw Boon Huan

Date : 27/07/2021

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 5702.60

Acknowledged By
Depot Safety : Ang Kiat Siang

Date : 27/07/2021

* This is computer generated document and does not require signature