



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2103249

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 10/05/2021
Reference CS3/III21005232/Gvf3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SKS 7108Y **Bill cancel refer to new invoice No. AC2105618 11/08/2021 \$461.00**

Insured Veh. SJR 9548P

Claim No.

Policy No.

Accident Date 25/04/2021

Inspection Date 28/04/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 28.04.2021 05.30pm	
- Dismantle Inspection 29.04.2021 01.47pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2105618

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 11/08/2021
Reference CS3/III21005232/Gvf3e2-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SKS 7108Y
Insured Veh. SJR 9548P
Claim No. MPC2021D0001939
Policy No. D21MPC0000770
Accident Date 25/04/2021
Inspection Date 28/04/2021

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Note: Pls discard Inv.AC2103249 dated 10/05/2021 \$140.17	
Subtotal	461.00
GST (7%)	32.27
Grand Total	493.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM