

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref: CS3/III21005232/Gvf3-1	
64 CECIL STREET			Date: 28/07/2021	
#05-02 IOB BUILDING SINGAPORE 049711			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJR 9548P		Veh. Inspected	SKS 7108Y
Policy No.	D21MPC0000770		Coverage (\$)	0.00
Claim No.	MPC2021D0001939		Excess (\$)	0.00
Assign From	CARINE KEK PHER SER		Assign Date	28/07/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/04/2021		Inspection Date	28/07/2021
Survey held at	SIN HOCK LEE MOTOR REPAIR 51 UBI AVENUE 1 #01-09 PAYA UBI INDUSTRIAL PARK . SINGAPORE 408933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				