



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|-----------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | | Ref: CS/FCI21008018/T1uf3e2 | |
| | | | Date: 17/12/2021 | |
| | | | Code: FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SBS 6338M | Veh. Inspected | SG 5831Z | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | D21002159MFBP | Excess (\$) | 0.00 | |
| Assign From | RACHELWU LIMEI | Assign Date | 28/07/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MAN A95 | c.c | 10518 | |
| Engine No. | HIDDEN | Year of Reg. | 2017 | |
| Chassis No. | WMAA95ZZ2G7003494 | Colour | GREEN | |
| Odometer | 163375 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 275/70 R22.5 | BRIDGESTONE | 8 mm | |
| L/H Front Tyre | 275/70 R22.5 | BRIDGESTONE | 8 mm | |
| R/H Rear Tyre | 275/70 R22.5 (D) | BRIDGESTONE | 8/8 mm | |
| L/H Rear Tyre | 275/70 R22.5 (D) | BRIDGESTONE | 8/8 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 24/07/2021 | Inspection Date | 29/07/2021 | |
| Survey held at | SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946 | | | |
| 5a. Remarks | | | | |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 2 Working Days | |