

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0605/2021/KS
DATE : 22-Jun-21
WIP : 32015

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/07/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

17 days exclude 1 PH & 3 Sundays

Johnny Boo 5 Oct 21

OWNER'S NAME : MR YEE BENG SOON
ADDRESS : BLK 314B ANCHORVALE LINK
#07-121
SINGAPORE 542314
TELEPHONE : HP +65 96694129
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210032738
VEHICLE NO : **SDM 3686 K**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 30/3/2021
ENGINE NO : CZD C30173
CHASSIS NO : WAUZZZF36M1079383
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE :
PLACE OF ACCIDENT :

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SDM 3686 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND INSTALL REAR PARKING AID AND REAR LID KICK SENSOR	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAILLIGHTS AND REAR LID WIPER AASY.	S/N \$	480.00	\$ 480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	\$ 480.00
4	TO INSTALL REAR SOLAR FILM FOR WINDSCREEN.	S/N \$	400.00	\$ 400.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	\$ 150.00
SUB TOTAL LABOUR CHARGES		:	\$ 1,920.00	\$ 1,870.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SDM 3686 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 1,870.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAILLIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS. S/N \$	480.00	\$ 480.00
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND REWELD REAR END PANELLING. TO REPAIR REAR SPARE WHEEL HOUSING. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	5,200.00	\$ 2,500.00
8	TO RESPRAY REAR BUMPER, REAR LID, HINGES, SPARE WHEEL HOUSING AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT. \$	4,300.00	\$ 1,650.00
9	TO REMOVE AND REINSTALL CENTER CONSOLE TO FACILITATE RENEWAL OF AIRBAG CONTROL UNIT. TO RENEW BOTH FRONT AND REAR SEATBELT ASSYS. S/N \$	1,800.00	\$ 1,800.00
10	TO CARRY OUT PRE & POST DIAGNOSTIC CHECK. S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		\$ 14,084.00	\$ 8,684.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 3686 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 1,634.00	\$	1,307.20
2	REAR BUMPER FIXING PARTS	1	\$ 211.00		
3	REAR BUMPER SPOILER	1	\$ 459.00	\$	367.20
4	REAR BUMPER TOWING COVER	1	\$ 43.00	\$	34.08
5	REAR BUMPER BRACKET	1	\$ 48.00		
6	REAR LID OPENING CONTROL UNIT	1	\$ 411.00		
7	REAR LID OPENING SENSOR LINE	1	\$ 206.00		
8	AERIAL FOR ACCESS AND START	1	\$ 71.00		
9	REAR LIGHT REFLECTOR - LH / RH	2	\$ 82.00	\$	32.56
10	LED LICENCE PLATE LIGHT - LH / RH	2	\$ 101.00		
11	LED TAIL LIGHT - LH / RH	2	\$ 1,852.00		
12	LED TAIL LIGHT TRIM - LH / RH	2	\$ 60.00		
13	REAR BUMPER REINFORCEMENT BEAM	1	\$ 651.00	\$	520.40
14	REAR BUMPER HOLDING STRAP CENTER	1	\$ 107.00		
15	REAR BUMPER GUIDE SECTION LH / RH	2	\$ 126.00		
16	REAR PARKING AID SENSOR	1	TBC		
17	REAR PARKING AID SENSOR SEAL RING	2	\$ 14.00		
18	REAR BUMPER WIRING SET	1	\$ 405.00		
19	REAR LID	1	\$ 3,508.00	\$	2,806.40
20	REAR LID PACKING ADHESIVE	1	\$ 19.00	\$	14.88
SUB TOTAL SPARE PARTS		:	\$ 10,008.00	\$	5,082.72

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 3686 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>5,082.72</i>
21	REAR LID ATTACHMENT PARTS	1	\$ 376.00		
22	REAR LID HINGE - LH / RH	2	\$ 295.00		
23	REAR LID LOCK	1	\$ 241.00		
24	REAR LID LOCK COVER	1	\$ 8.00		
25	REAR LID BOWDEN CABLE	1	\$ 39.00		
26	REAR LID SERVOMOTOR	1	\$ 278.00		
27	REAR LID STRIKER PLATE	1	\$ 66.00		
28	REAR LID GASKET FLAP	1	\$ 205.00		
29	REAR LID PUSH BUTTON	1	\$ 1,389.00		
30	"AUDI" EMBLEM	1	\$ 138.00	\$	<i>110.00</i>
31	"Q3" EMBLEM	1	\$ 99.00	\$	<i>79.04</i>
32	REAR WINDSCREEN	1	\$ 958.00	\$	<i>766.00</i>
33	REAR WINDSCREEN PRIMER	1	\$ 20.00	\$	<i>15.76</i>
34	REAR WINDSCREEN SPOILER - LH / RH	2	\$ 422.00	\$	<i>337.60</i>
35	REAR WHEEL ARCH COVER - LH / RH	2	\$ 536.00	\$	<i>428.80</i>
36	REAR END PANEL	1	\$ 268.00	\$	<i>248.80</i>
37	REAR END PANEL REINFORCEMENT	1	\$ 687.00		
38	REAR END PANEL CONNECTING PLATE LH / RH	2	\$ 82.00		
39	REAR END PANEL TRIM	1	\$ 189.00		
40	REAR LUGGAGE COMPARTMENT BOARD	1	\$ 894.00		
SUBTOTAL SPARE PARTS		:	\$ 7,190.00	\$	<i>7,068.72</i>

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 3686 K

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	7,068.72
41	REAR SILENCER HEAT SHIELD	1	\$	116.00	
42	FRONT THREE POINT SEAT BELT - LH / RH	2	\$	1,744.00	\$ 1,427.60
43	FRONT SEAT BELT HEIGHT ADJUSTER - LH / RH	2	\$	342.00	\$ 273.60
44	REAR THREE POINT SEAL BELT - LH / RH	2	\$	980.00	\$ 784.00
45	AIRBAG CONTROL UNIT	1	\$	1,457.00	\$ 1,165.60
46	ARYCLIX SEALANT	S/N	\$	180.00	\$ 180.00
47	CAVITY WAX	S/N	\$	140.00	\$ 140.00
48	STONE CHIP	S/N	\$	180.00	\$ 180.00
49	METAL FILLER POWDER	S/N	\$	280.00	\$ 280.00
50	REAR WINDSCREEN SEALANT	S/N	\$	200.00	\$ 200.00
51	REAR NO. PLATE	S/N	\$	60.00	\$ 60.00
52	SUNDRIES		\$	450.00	\$ 87.60
TOTAL SPARE PARTS				\$ 23,327.00	\$ 11,847.12
TOTAL LABOUR CHARGES				\$ 14,084.00	\$ 8,684.00
GRAND TOTAL				\$ 37,411.00	\$ 20,531.12

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bk030/09/21



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT