

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0626/2021/GW
DATE : 3-Aug-21
WIP : 37388

Jaslin.
\$1852

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY

YOUR INSURED VEH NO : SFN 911 B

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LER ZHI KANG(LU ZHIKANG)
ADDRESS : 164 CANBERRA DRIVE
#08-55
SINGAPORE 768001
TELEPHONE : HP +65 98534199
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : D21MPC0003035
VEHICLE NO : SCQ 9780 Y
MODEL CODE : AUDI A5 2.0 SPORTBACK 2.0 TFSI
MODEL YEAR : 14/9/2020
ENGINE NO : DEM024936
CHASSIS NO : WAUZZZF56LA021158
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jul-21
PLACE OF ACCIDENT : PENSHURST PLACE



AIG VOLVO BLE LTD



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCQ 9780 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING ATD	S/N \$ 480.00 ✓	
3	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 500	
4	TO RESPRAY FRONT BUMPER.	\$ 1,000.00 550	
5	TO RE-APPLY PAINT COATING ON AFFECTED AREA. (BY OWNER)	TBC 130	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,872.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCQ 9780 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rep</i>	1	\$ 2,342.00	+
2	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	1	\$ 262.00	+
3	FRONT BUMPER CLOSING ELEMENT	1	\$ 262.00	+
4	FRONT BUMPER SECURING STRIP	2	\$ 71.00	+
5	SUNDRIES <i>mem</i>		\$ 350.00	+
TOTAL SPARE PARTS			\$ 3,287.00	
TOTAL LABOUR CHARGES			\$ 2,872.00	
GRAND TOTAL			\$ 6,159.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *03/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT