

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008029/APA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070149707
Claimant Vehicle No :	SLK8467J	Insured Vehicle No :	SMW1004H
Date of Loss:	25/07/2021	Nature of Claim:	TP
		Claim No:	3280773475SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8467J	Engine No:	1ZRX576174
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104551633
Reg. Date:	01/02/2017 (Man. Year: 2016)	Odometer:	79458 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,622.44	4,895.80	3,726.64	43.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	2,070.00	3,250.00	61.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,942.44	6,965.80	6,976.64	50.04
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	13,942.44	5,600.00	8,342.44	59.83
+ GST 7.00/7.00% (S\$)	975.97	392.00	583.97	59.83
Nett Amount (S\$)	14,918.41	5,992.00	8,926.41	59.83
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,799.45		
Global Sum Settlement (S\$)		6,700.00		

INSPECTION

Date of Assignment:	27/07/2021		
Date Inspected:	27/07/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	925.30 FL	*795.00 FL
2	1		*BOOTLID LOGO	Necessary	89.60 FL	*89.60 FL
3	1		*BOOTLID COROLLA EMBLEM	Necessary	85.20 FL	*85.20 FL
4	1		*BOOTLID ALTIS EMBLEM	Necessary	86.30 FL	*86.30 FL
5	1		*BOOTLID OUTER CHROME GARNISH	Cracked	325.80 FL	*233.00 FL
6	2		*BOOTLID NUMBER PLATE LAMPS	Not Necessary	159.20 FL	*- FL
7	1		*BOOTLID INNER TRIM	Deformed	285.30 FL	*285.30 FL
8	2		*BOOTLID LAMPS	Cracked	651.40 FL	*651.40 FL
9	2		*BOOTLID LAMPS INNER SEALER	Not Necessary	80.00 FL	*- FL
10	2		*BOOTLID LAMPS INNER COVER	Not Necessary	104.60 FL	*- FL
11	1		*BOOTLID INNER LOCK	Damaged	148.60 FL	*148.60 FL
12	1		*BOOTLID LOCK CATCH	Not Necessary	55.20 FL	*- FL
13	1		*BOOTLID WEATHERSTRIP	Cut	197.60 FL	*197.60 FL
14	2		*BOOTLID HINGES	Bent	176.40 FL	*176.40 FL
15	4		*BOOTLID STOPPERS	Not Necessary	120.00 FL	*- FL
16	1		*REAR BUMPER	Deformed	598.70 FL	*598.70 FL
17	2		*REAR BUMPER SIDE RETAINERS (LONG)	Not Necessary	185.20 FL	*- FL
18	2		*REAR BUMPER SIDE RETAINERS (SHORT)	Necessary	117.80 FL	*117.80 FL
19	2		*REAR REINFORCEMENT BRACKETS	Dented	290.40 FL	*110.00 FL
20	1		*REAR BUMPER REINFORCEMENT	Dented	458.30 FL	*395.00 FL
21	2		*REAR BUMPER REFLECTORS	Not Necessary	178.60 FL	*- FL
22	2		*TAILLAMPS	Cracked	900.66 FL	*776.00 FL
23	2		*TAILLAMPS INNER SEALER	Not Necessary	80.00 FL	*- FL
24	2		*TAILLAMPS BRACKETS	Not Necessary	77.00 FL	*- FL
25	2		*TAILLAMPS PANELS	Not Necessary	490.40 FL	*- FL
26	1		*END PANEL	Dented	598.70 FL	*598.70 FL
27	1		*END PANEL TOP GARNISH	Deformed	225.90 FL	*225.90 FL
28	1		*SPARE TYRE PANEL	Repair	698.70 FL	*- FL
29	1		*SPARE TYRE PANEL TOP BOARD	Deformed	385.20 FL	*385.20 FL
30	2		*REAR FENDER INNER COWLING	Not Necessary	371.40 FL	*- FL
31	2		*REAR FENDER INNER TRIM	Not Necessary	718.40 FL	*- FL
32	1		*REAR AIR VENT	Not Necessary	98.70 FL	*- FL
33	1		*SET REAR NUMBER PLATE WITH CASING	Dented	50.00 FS	*50.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*SET BOOTLID CHROME GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
36	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
37	2		*END PANEL /FENDER SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*SET REAR REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
39	2		*SET TAILLAMPS CLIPS	Necessary	60.00 FS	*20.00 FS
40	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FS	*10.00 FS
41	2		*SETS REAR FENDER INNER COLWING CLIPS	Not Necessary	60.00 FS	*- FS
42	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
43	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
44	1		*REAR SMART KEY SENSOR	Damaged	158.70 FL	*158.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,153.26	6,424.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,530.82	1,528.60
Total Parts (\$\$)	8,622.44	4,895.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS ,REPLACE BEAT ,WELD ,REALIGN STRAIGHTEN MEMBER	New	2,000.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	2,000.00	900.00
3	TO TUFFCOAT AFFECTED AREA	New	150.00	60.00
4	TO REMOVE /REFIT REAR WINDSCREEN	New	150.00	0.00
5	TO CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
6	TO REMOVE /REFIT INTERIOR UPHOLSTERY	New	180.00	60.00
7	TO REMOVE/REFIT /REPLACE BOOTLID MECHANISM	New	150.00	60.00
8	TO REMOVE /REFIT REPLACE REAR SENSOR AND DISTANCE SETTLING	New	120.00	50.00
9	TO REMOVE/REFIT REVERSE CAMERA	New	120.00	50.00
10	LABOUR TO APPLY SEALANT TO AFFECTED AREAS	New	250.00	60.00
11	TO REMOVE/REFIT WIRING CHECK ON REAR TAILLAMPS	New	120.00	30.00
Gross Labour Cost (\$\$)			5,320.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >