

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: INDIA	DATE	23/07/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SMW8566G	KPT30A1U5LP318110	
MODEL	: SSANGYONG TIVOLI	Xiao Tony	
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 23-Jul-21
		TIME	: 08:10HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,890.40	\$ 1,890.40
2	TAILGATE LOGO	1	\$ 150.00	\$ 150.00
3	TAILGATE EMBLEM 'TIVOLI'	1	\$ 90.00	\$ 90.00
4	TAILGATE EMBLEM 'SSANGYONG'	1	\$ 110.00	\$ 110.00
5	TAILGATE LOCK <i>Damaged</i>	1	\$ 322.50	\$ 322.50
6	TAILGATE INNER TRIM <i>Cracked</i>	1	\$ 510.20	\$ 510.20
7	TAILGATE WEATHER STRIP <i>New</i>	1	\$ 210.00	\$ 210.00
8	TAILGATE WINDSCREEN MOULDING <i>New</i>	1	\$ 190.00	\$ 190.00
9	TAILGATE KEYNESS SENSOR <i>New</i>	1	\$ 280.20	\$ 280.20
10	TAILGATE NUMBER PLATE GARNISH <i>New</i>	1	\$ 160.00	\$ 160.00
11	REAR BUMPER UPPER <i>3 Dented</i>	1	\$ 1,245.80	\$ 1,245.80
12	REAR BUMPER LOWER	1	\$ 650.20	\$ 650.20
13	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 64.20	\$ 128.40
14	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 140.00	\$ 280.00
15	REAR BUMPER REINFORCEMENT <i>Cracked</i>	1	\$ 455.50	\$ 455.50
16	REAR BUMPER REINFORCEMENT BRACKET <i>4th Dented</i>	1	\$ 180.20	\$ 180.20
17	REAR BUMPER REINFORCEMENT INNER HOLDER <i>2nd</i>	4	\$ 80.00	\$ 320.00
18	REAR BUMPER BRAKE LIGHT <i>Cracked</i>	1	\$ 250.00	\$ 250.00

Damaged

19	REAR END PANEL <i>Revised</i>	1	\$ 820.50	\$ 820.50
20	REAR END PANEL TOP GARNISH <i>Revised</i>	1	\$ 211.50	\$ 211.50

6072.30
5465.07

TOTAL PRICE \$ 8,455.40

LESS 10% \$ 845.54

SUB TOTAL PRICE \$ 7,609.86

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR STICKERE <i>New</i>	1	\$ 500.00	\$ 500.00
2	REAR NUMBER PLATE <i>Revised</i>	1	\$ 20.00	\$ 20.00
3	TAILGATE INNER TRIM CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
4	TAILGATE WINDSCREEN MOULDING <i>New</i>	1	\$ 80.00	\$ 80.00
5	REAR BUMPER CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
6	REAR END PANEL SEALANT <i>New</i>	1	\$ 100.00	\$ 100.00
7	REAR END PANEL TOP GARNISH CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
8	REVERSE SENSOR <i>Revised</i>	1	\$ 220.00	\$ 220.00
TOTAL			\$	980.00

710

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	80	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	80	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 100.00	30	
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 180.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓	
8	TRANSFER TAILGATE WINDSCREEN	\$ 120.00	✓	

TOTAL

\$3,210.00

ESTIMATE REPORT

TOTAL PARTS COST : \$

TOTAL LABOUR COST : \$

TOTAL REPAIR COST : \$

APPROVED DETAILS

SURVEYOR :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin L
H/S 26/07/21.

06 Days
Total: 8175.07
H/S: 6.5K.