

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

ANG BENG SOON EDWARD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TPAIG.
Xiao Eng.

28th July 2021

GP71216645

Accident date: 26th JULY 2021

Estimated repair costs for vehicle no: SMD9649U Honda Shuttle 1.5A (SEP 2018)

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid <i>Distorted</i>		\$1,250.00 <i>1180.</i>
2	2	Rear Boot Lid hinges <i>new</i>	\$155.00	\$310.00
3	1	Rear boot lid rubber <i>new</i>		\$205.00 <i>366.</i>
4	1	Rear Boot Lid inner trim <i>cracked</i>		\$680.00
5	1	boot lid inner lock <i>new</i>		\$203.10
6	2	rear boot lid shock absorber <i>new</i>	\$210.00	\$420.00
7	1	Rear boot lid windscreen inner seal <i>new</i>		\$128.00
8	8	Rear boot lid center garnish clips <i>new</i>	\$5.50	\$44.00 <i>20</i>
9	1	Rear boot lid centre garnish <i>cracked</i>		\$285.10
10	1	Rear boot lid emble logo <i>new</i>		\$60.00
11	1	Rear Boot Lid SHUTTE logo <i>new</i>		\$40.00
12	1	Rear Boot Lid Hybrid logo <i>new</i>		\$48.00
13	1	boot lid centre moulding <i>new</i>		\$385.20
14	1	boot lid centre moulding clips <i>new</i>		\$80.00
15	2	Rear Boot Lid side reflector <i>new</i>	\$375.00	\$750.00 <i>375</i>
16	2	Rear tail lamp <i>new</i>	\$558.00	\$1,116.00 <i>558</i>
17	2	Rear Number Plate lamp <i>new</i>	\$58.00	\$116.00
18	1	Rear Number Plate <i>new</i>		\$50.00
19	2	Rear Bumper side reflector <i>new</i>	\$85.00	\$170.00
20	1	Rear Bumper Reinforcement <i>new</i>		\$425.10
21	1	Rear bumper <i>new</i>		\$1,080.00
22	2	Rear bumper side bracket <i>new</i>	\$112.00	\$224.00 <i>78.</i>
23	8	Rear bumper clips <i>new</i>	\$5.00	\$40.00
24	1	Rear bumper Sponge <i>new</i>		\$168.20
25	1	Rear Bumper reverse sensor <i>new</i>		\$350.00 <i>200(SN)</i>
26	1	Rear end panel <i>new</i>		\$740.00
27	1	Rear end Panel top garnish <i>new</i>		\$384.00
28	1	Spare Tyre Panel top cover <i>new</i>		\$415.00
29	1	Rear spare tyre panel sealant <i>new</i>		\$280.00
30	1	rear exhaust chome pipe <i>new</i>		\$160.00

Subtotal :- \$10,606.70

H461.12.

3568.96 S.N: 200

Labour charges

Remove / refix rear windscreen

gum

remove / refix rear cushion

Remove / refix rear reverse sensor

Tuff kote

To Check Wiring System

Panel beating

Spray painting charges

\$120.00 ✓

\$50.00 ✓

\$120.00 60

\$120.00 50

\$120.00 50

\$60.00 30

\$800.00 600

\$800.00 600

\$2,190.00

Total:-

\$12,796.70

total: 5328.96

t/s: A.2K.
05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: