

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21008036/EUF3N2**Date:** 19/11/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001743622

Claimant Vehicle No : PD1131M**Insured Vehicle No :** YP3136S

Date of Loss: 26/07/2021

Nature of Claim: TP

Claim No: 260541

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **PD1131M**

Make & Model: VOLVO B8R, 7.7 D (A)

Engine No: D8500302

Reg. Date: 12/12/2020 (Man. Year: 2019)

Chassis No: YV3T7U523LA199491

Colour: Multi-colour

Odometer: 25155 km

Engine Capacity: 7698 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5

Rear Tyre Size: 295/80R22.5

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,750.00	1,750.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	570.00	370.00	200.00	35.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,320.00	2,120.00	200.00	8.62
+ GST 7.00/7.00% (S\$)	162.40	148.40	14.00	8.62
Nett Amount (S\$)	2,482.40	2,268.40	214.00	8.62

INSPECTION

Date of Assignment: 29/07/2021

Date Inspected: 30/07/2021

Inspected At:

7 OLD TOH TUCK ROAD

SINGAPORE 597648

REPAIRER: CONNECT3

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Nov 2021)	
Parts:	N/A	VOLVO B8R 7.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PD1131M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH REAR VIEW MIRROR ASSY	Cut	1,750.00 FS	*1,750.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,750.00	1,750.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	20.00	20.00
2	LABOUR CHARGES	New	300.00	200.00
3	SPRAY PAINTING	New	250.00	150.00
Gross Labour Cost (\$)			570.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >