

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21008036/EUF3N2
Date: 21/03/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001743622		
Claimant Vehicle No :	PD1131M	Insured Vehicle No :	YP3136S		
Date of Loss:	26/07/2021	Nature of Claim:	TP	Claim No:	260541

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PD1131M	Engine No:	D8500302
Make & Model:	VOLVO B8R, 7.7 D (A)	Chassis No:	YV3T7U523LA199491
Reg. Date:	12/12/2020 (Man. Year: 2019)	Odometer:	25155 km
Colour:	Multi-colour		
Engine Capacity:	7698 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,750.00	1,575.00	175.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	570.00	370.00	200.00	35.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,320.00	1,945.00	375.00	16.16
+ GST 7.00/7.00% (S\$)	162.40	136.15	26.25	16.16
Nett Amount (S\$)	2,482.40	2,081.15	401.25	16.16

INSPECTION

Date of Assignment:	29/07/2021		
Date Inspected:	30/07/2021	Inspected At:	7 OLD TOH TUCK ROAD SINGAPORE 597648 REPAIRER: CONNECT3
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 14 Mar 2022)
Parts:	N/A	VOLVO B8R 7.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/PD1131M/21/03/2022 16:27	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH REAR VIEW MIRROR ASSY	Cut	1,750.00 F	*1,750.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					1,750.00	1,750.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	175.00
Total Parts (\$\$)					1,750.00	1,575.00

LKK Auto Consultants Pte Ltd/PD1131M/21/03/2022 16:27. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING	New	20.00	20.00
2	LABOUR CHARGES	New	300.00	200.00
3	SPRAY PAINTING	New	250.00	150.00
Gross Labour Cost (\$\$)			570.00	370.00

LKK Auto Consultants Pte Ltd/PD1131M/21/03/2022 16:27. Not valid without Reference section.

< END OF ESTIMATES >