



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 28.07.2021
Emailed : 21.10.2021, 11.50am
Date Survey : 29.07.2021

VEHICLE NO : SJU 7937 Y
MODEL : MIT ECLIPSE CROSS 1.5 SPORTS
WIP : 13590

Material	:	\$	<u>11,304.37</u>
Labour	:	\$	<u>10,205.00</u>
Sub-Total	:	\$	<u>21,509.37</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>800.00</u>
Total	:	\$	<u>20,709.37</u>
GST 7%	:	\$	<u>1,449.66</u>
Grand Total	:	\$	<u>22,159.03</u>
Finalise By/Date	:		<u>LOI / 21/10/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/07/2021	Cust No/Name KCV19267/REDDIPALLI ASHOK RAMAMURTHY Reg No/Reg Date SJU7937Y / 19/11/2018 Date In/Mileage 29/07/2021/ 63249 Chassis/Package JMAXTGK1WJZ002846 Engine No 4B40DR9185 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF Colour/Trim CO2 BRONZE METALLIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/10/2021/ 09:08	BLE	260 / AiTing	13590			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, RH REAR FENDER, RH REAR DOOR, RH FRONT DOOR, RH FRONT FENDER, FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 3375.00
E PNT98000 RESPRAY ON FRONT BUMPER, REAR BUMPER, RH FRONT FENDER, RH FRONT DOOR, RH REAR DOOR, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2100.00
E PNT88000 REMOVE & REINSTALL RH REAR DOOR COMPONENTS TO NEW PANEL								✓ 120.00
E PNT88000 REMOVE & REINSTALL RH FRONT DOOR COMPONENTS TO NEW PANEL								✓ 120.00
M SUNDRY REPLACE RH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								✓ 30.00
E PNT88000 REMOVE & REINSTALL ALL REAR SEATS, TRIMS, CARPETS, REAR FLOOR BOARD, AND ALL OTHER ATTACHMENTS TO FACILITATE REPAIR								✓ 450.00
E PNT88000 REMOVE & REINSTALL ROOF LINING TO FACILITATE REPAIR								✓ 450.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								✓ 120.00
A 34900099 REMOVE & REPLACE RH REAR UNDERCARRIAGE PARTS								✓ 450.00
E PNT88000 REMOVE & REINSTALL FRONT PARKING ASSIST SENSOR TO FACILITATE REPAIR								✓ 80.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR								✓ 80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								✓ 40.00

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV19267/REDDIPALLI ASHOK RAMAMURTHY Reg No/Reg Date SJU7937Y / 19/11/2018 Date In/Mileage 29/07/2021/ 63249 Chassis/Package JMAXTGK1WJZ002846 Engine No 4B40DR9185 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF Colour/Trim CO2 BRONZE METALLIC/ BK BLACK
29/07/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/10/2021/ 09:08	BLE	260 / AiTing	13590			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								✓ 80.00
SUPPLY BODY PANEL SEALANT								
M SUNDRY								✓ 30.00
SUNDRIES								
E PNT88000								1350.00
REPLACE RH ROCKER PANEL & RH REAR INNER QUARTER PANEL				→ Supp.				
E PNT98000								700.00
RESPRAY RH ROCKER PANEL, & RH REAR INNER QUARTER PANEL				→ Supp.				
S TYRESALES1								✓ 480.00
SUPPLY RH REAR TIRE (YOKOHAMA AE61 225/55R18)								
X EXC								-800.00
EXCESS								
X FACE,RR BUMPER					1.00	✓ 556.00	23.00	428.12
X EXTENSION,RR BUMPER					1.00	✓ 152.00	23.00	117.04
X BRKT,R/BMPR FACE SIDE,RH					1.00	✓ 25.00	23.00	19.25
X CLIP,FR BUMPER					8.00	✓ 4.00	23.00	24.64
X PANEL,QTR,OTR RH					1.00	✓ 866.00	23.00	666.82
X GARNISH,SIDE SILL,RH					1.00	✓ 91.00	23.00	70.07
X GARNISH,FR DOOR,RH					1.00	✓ 241.00	23.00	185.57
X GARNISH,RR DOOR,RH					1.00	✓ 160.00	23.00	123.20
X MOULDING,R/DOOR PROTECT,RH					1.00	✓ 105.00	23.00	80.85
X GARNISH,QTR PANEL,RH					1.00	✓ 181.00	23.00	139.37
X MOULDING,FR WHEEL ARCH,RH					1.00	✓ 151.00	23.00	116.27
X MOULDING,RR WHEEL ARCH,RH					1.00	✓ 159.00	23.00	122.43
X SHIELD,RR WHEEL,RR RH					1.00	✓ 38.00	23.00	29.26
X PANEL ASSY,RR DOOR,RH					1.00	✓ 942.00	23.00	725.34
X MOULDING,R/DR SASH,UPR RH					1.00	✓ 114.00	23.00	87.78
X PANEL ASSY,FR DOOR,RH					1.00	✓ 954.00	23.00	734.58
X MOULDING,F/DR SASH,UPR RH					1.00	✓ 119.00	23.00	91.63
X MIRROR ASSY,DOOR,RH					1.00	✓ 824.00	23.00	634.48
X FENDER,FR RH					1.00	✓ 541.00	23.00	416.57
X FACE,FR BUMPER					1.00	✓ 718.00	23.00	552.86
X HEADLAMP ASSY,RH					1.00	✓ 1986.00	23.00	1529.22

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/07/2021	<table> <tr><td>Cust No/Name</td><td>KCV19267/REDDIPALLI ASHOK RAMAMURTHY</td></tr> <tr><td>Reg No/Reg Date</td><td>SJU7937Y / 19/11/2018</td></tr> <tr><td>Date In/Mileage</td><td>29/07/2021/ 63249</td></tr> <tr><td>Chassis/Package</td><td>JMAXTGK1WJZ002846</td></tr> <tr><td>Engine No</td><td>4B40DR9185</td></tr> <tr><td>Make/Model</td><td>MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF</td></tr> <tr><td>Colour/Trim</td><td>CO2 BRONZE METALLIC/ BK BLACK</td></tr> </table>	Cust No/Name	KCV19267/REDDIPALLI ASHOK RAMAMURTHY	Reg No/Reg Date	SJU7937Y / 19/11/2018	Date In/Mileage	29/07/2021/ 63249	Chassis/Package	JMAXTGK1WJZ002846	Engine No	4B40DR9185	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF	Colour/Trim	CO2 BRONZE METALLIC/ BK BLACK
Cust No/Name	KCV19267/REDDIPALLI ASHOK RAMAMURTHY														
Reg No/Reg Date	SJU7937Y / 19/11/2018														
Date In/Mileage	29/07/2021/ 63249														
Chassis/Package	JMAXTGK1WJZ002846														
Engine No	4B40DR9185														
Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF														
Colour/Trim	CO2 BRONZE METALLIC/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/10/2021/ 09:08	BLE	260 / AiTing	13590

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LAMP ASSY,COMB,RR RH	1.00	693.00	23.00	533.61
X WHEEL,DISC RHR	1.00	1102.00	23.00	848.54
X HUB ASSY,RHR WHEEL	1.00	434.00	23.00	334.18
X ARM ASSY,RR SUSP,UPR	1.00	131.00	23.00	100.87
X LINK,RR SUSP ASSIST	1.00	79.00	23.00	60.83
X ARM ASSY,RR SUSP TRAIL,RH	1.00	504.00	23.00	388.08
X SHOCK ABSORBER,RR SUSP	1.00	296.00	23.00	227.92
X SIDE SILL,FR FLOOR,OTR RH	1.00	792.00	23.00	609.84
X DUCT,RR VENTILATOR	1.00	39.00	23.00	30.03
X SIDE EXTENSION	1.00	436.00	23.00	335.72
X BRACE,RR PILLAR,RH	1.00	57.00	23.00	43.89
X REINF,RR PILLAR,RH	1.00	477.00	23.00	367.29
X REINF,RR PILLAR,LWR RH	1.00	74.00	23.00	56.98
X PANEL,QTR,LWR INR RH	1.00	286.00	23.00	220.22
X EXTENSION,QTR PANEL,INR RH	1.00	189.00	23.00	145.53
X EXTN,QTR PANEL,RR LWR RH	1.00	97.00	23.00	74.69
X VALVE,TIRE	1.00	40.00	23.00	30.80

Z TEXT

AIG OD CLAIM, UIL CLAIM GBC4510D
DOA : 28.07.21
SURVEYOR STEVE LKK 29.07.21
POLICY NO : 1800134321-02

REPAIR 15 DAYS

19

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	11,304.37	Nett	20,709.37
Labour	9,545.00	7% GST on	20709.37
Standard Menu	0.00		1449.66
Specialist Job	480.00	Total Payable	22,159.03
Diagnostics Job	0.00		
Sundry/Others	-620.00		
Total(w/o GST)	20,709.37		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SJU 7937 Y**

<u>Materials</u>		<u>Cost (\$)</u>
1	Side sill, Fr floor, Otr RH	792.00 / DD
2	Duct, RR ventilator	39.00 / BR
3	Side Extension	436.00 / DD
4	Brace, RR pillar, RH	57.00 / DD
5	Reinf, RR pillar, RH	477.00 / DD
6	Reinf, RR pillar, Lwr RH	74.00 / DD
7	Panel, Qtr, Lwr inr RH	286.00 / DD
8	Extension, Qtr panel, Inr RH	189.00 / DD
9	Valve, Tire	40.00 / nec

Total	2,390.00
Less 23%	549.70
Total Materials	1,840.30

	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace RH rocker panel, & RH rear inner Quarter panel	1350.00 /
2	Respray RH rocker panel, & RH rear inner Quarter panel	700.00 /


Total Labour	2,050.00
--------------	----------

Taxable Amount	3,890.30
7% GST	272.32

Grand total	<u>4,162.62</u>
--------------------	------------------------

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: STU 7937Y WIP: 13590 (ADDITIONAL PARTS CHANGE)

SINO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Brace RR Pillar RH	? / SUPP		/ 00	
2	Reinforcement RR Pillar RH	? / SUPP		/ 00	
3	Reinforcement RR Pillar LWR RH	? / SUPP		/ 00	Stop
4	Panel QTR LWR Inper RH	? / SUPP		/ 00	10/8/21
5	Extension QTR Panel INR RH	? / SUPP		/ 00	
6	Extension QTR Panel RR LWR RH	? / SUPP		/ 00	
7		? / SUPP			
8	PLT NUMBER PLATE w/ CASING	? / SUPP			
9	Valve, Tire RR type	? / SUPP			. 4250C.386 ← Part No.
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

MODEL: Eclipse

SURVEYOR: Star

Work Order: R001501
 License: SJU 7937 Y
 Technician: 106 WENG SOON
 Mileage: 63249
 Date: 3.8.21 10:27

MITSUBISHI ECLIPSE CROSS 16" & 18" 2018-

Front : Left

Actual	Before	Specified Range
0°22'	0°20'	0°00' 0°30'
1°57'*	1°57'*	2°00' 3°00'
0°63'	-0°05'*	0°00' 0°06'
11°17'*	11°19'*	11°30' 14°30'
11°39'	11°39'	11°30' 15°00'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°19'	0°16'	0°00' 0°30'
2°42'	2°42'	2°00' 3°00'
0°03'	-0°04'*	0°00' 0°06'
12°12'	12°16'	11°30' 14°30'
12°32'	12°32'	11°30' 15°00'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°03'	0°04'	-0°45' 0°45'
-0°44'	-0°44'	-0°45' 0°45'
-0°55'*	-0°57'*	-0°45' 0°45'
0°05'	-0°09'*	0°01' 0°11'

Rear : Left

Actual	Before	Specified Range
-0°34'	-0°20'*	-0°55' -0°25'
0°06'	0°31'*	0°06' 0°11'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°28'	-0°28'	-0°55' -0°25'
0°08'	0°26'*	0°06' 0°11'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°07'	0°09'	-0°45' 0°45'
0°15'	0°57'*	0°11' 0°21'
-0°01'	0°02'	

Ref No: SSV12511
offer to us
part for unit to bags
is all bags send
to JSD
to JSD
to JSD

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	GK1W 2018MY

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition			
	MPI/GDI/DIESEL	GAS_0C640000		No DTCs				
	AT/CVT/A-MT/C-SST	CVT_14080300		No DTCs				
	4WS/Electric Power Steering	EPS_45840000		No DTCs				
	ABS/ASC/ASTC/WSS	ASC_42080014		No DTCs				
	SRS-AIR BAG	SRS_81047305		No DTCs				
	Air Conditioner	AC_80080017		No DTCs				
	ETACS	ETACS_83040800		No DTCs				
	TPMS (with KOS)	ETACS_83040800	B1A10	Keyless/KOS key 1 low battery	Active			
	Meter	METER_84088001		No DTCs				
	Steering Angle Sensor	GS_SAS_47000100_FordMUT3		No DTCs				
	AND	AND_8C080002		Non-target System				
	AUDIO (IntelligentDisplay)	AUDIO_8D080002		No DTCs				
	LIN	ETACS_83040800		Non-target System				
	KOS/OSS/IMMO/Keyless (with KOS)	ETACS_83040800	B1A10	Keyless/KOS key 1 low battery	Active			

All DTCs

2021.09.30

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	CORNER SENSOR/SONAR	SONAR_9D080000		No DTCs		
	ACC/FCM	ACCSFCM_4B080004		Non-equipped System or Communication Error		
	Multi Around Monitor	CAMERA_94080100		No DTCs		
	EPB	EPB_4C080000		No DTCs		
	Gateway	GW_C1000000		Non-equipped System or Communication Error		
	FCM/LDW/AHB	ADAS_4B080003		No DTCs		
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		
	HUD	HUD_9E080000		No DTCs		