



MOTORSPORTS

25 Kaki Bukit Road 4 #06-38 Synergy@KB

Singapore 417800

Tel: 92373644 Fax: 64514516

Vehicle No : SMQ 5428 Z

Model : Toyota Wish

Chassis No : JTDGG20W305001673

D.O.A : 27 JULY 2021

List Item :

01ps Bonnet <i>Repr</i>	\$ 825.00 +
01ps Bonnet hinges (LH) <i>new</i>	\$ 125.00 +
01ps Front bumper <i>Del</i>	\$ 692.00 ✓
01ps Front bumper side retainer (LH) <i>Repr</i>	\$ 125.00 ✓
01ps Front bumper bracket <i>new</i>	\$ 155.00 +
01ps Front bumper reinforcement <i>Bent</i>	\$ 485.00 327
01ps Front bumper sponge <i>cracked</i>	\$ 275.00 (31)
01ps Front bumper lower grill (LH) <i>new</i>	\$ 120.00 +
01ps Front bumper fog lamp assy (LH) <i>new</i>	\$ 380.00 +
01ps Front support panel top garnish	\$ 155.00 +
04ps Front support panel top garnish clip @ \$7.50 x 4 <i>new</i>	\$ 30.00 +
01ps Front headlamp(LH) <i>Cracked</i>	\$ 1038.00 ✓
01ps Front headlamp bracket (LH) <i>new new</i>	\$ 88.00 +
01ps Front headlamp panel (LH) <i>Repr</i>	\$ 433.00 +
01ps Front Fender (LH) <i>Del</i>	\$ 975.00 786
01ps Front Fender inner shield(LH) <i>Del</i>	\$ 255.00 ✓
08ps Front Fender inner shield clip (LH) <i>new</i> @ \$3.50 x 08	\$ 28.00 ✓
01ps Front Fender quarter glass <i>new new</i>	\$ 285.00 +

List price : \$ 6469.00

Less 25% : (\$ 1617.25)

Total : \$ 4851.75



MOTORSPORTS

25 Kaki Bukit Road 4 #06-38 Synergy @ KB
Singapore 417800
Tel: 92373644 Fax: 64514516

01ps Front Shock absorber (LH)	\$ 535.00	X
01ps Front Lower arm (LH)	\$ 569.00	X
01ps Front knuckle arm (LH)	\$ 538.00	X
01ps Front knuckle arm bearing (LH)	\$ 295.00	X
01ps Front stabilizer bar linkage (LH)	\$ 238.00	X
01ps Front Tie rod end (LH)	\$ 195.00	X

List price : \$ 2370.00

Less 25% (\$ 592.50)

Total : \$ 1777.50

Special Nett :

01ps Front sports Rims (LH)	\$ 550.00	X
01ps Front tyres (LH)	\$ 380.00	X

Total : \$ 930.00



MOTORSPORTS

25 Kaki Bukit Road 4 #06-38 Synergy@KB
Singapore 417800
Tel: 92373644 Fax: 64514516

Labour :

- 01) To supply labour and parts to repair and replace above mentioned parts
- 02) To supply labour and paint to spray accident affected area
- 03) To supply labour to re-wire replace parts
- 04) To supply labour to spray anti rust on panel
- 05) To supply labour to replace under carriage parts
- 06) To supply labour to conduct wheel alignment
- 07) To supply labour to straighten chassis frame

\$ 1600.00 ~~700~~
\$ 900.00 ~~700~~
\$ 90.00 ~~30~~
\$ 90.00 ~~40~~
\$ 280.00 ~~80~~
\$ 180.00 ~~80~~
\$ 180.00 ~~X~~

TOTAL : \$ 3320.00

Total Parts : \$ 7559.25
Total labour \$ 3320.00
Total \$ 10879.25

Admin Lj

L/s 02/08/21

06 Days

Total: 4544.

2/S: 3.6k

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: