



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
Teo Hung Cher (zhang Hanzhi)	Cust No/Name /TEO HUNG CHER (ZHANG HANZHI)
3A ONTARIO AVE	Reg No/Reg Date SLS2197K / 14/09/201
#04-07	Date In/Mileage / 0
SINGAPORE 576192	Chassis No KNAFZ411MJ5740972
Contact No Mobile: 96721720	Engine No G4FGHH678895
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	12/07/2021/ 19:38	TLE	261 / Edwin Caina	35996			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000				2 X 640 + 80				1280
RENEW FR BUMPER , FR BUMPER BODY KIT & RHF FENDER								2560.00
REPAIR RHF DOOR								
E PNT98000				275				1925
RESPRAY RHF DOOR , RHF FENDER , FR BUMPER & FR BUMPER BODY KIT					3 X	550 +	275	2750.00
M SUNDRY								80.00
RENEW RHF SPORT RIM & TRANSFER TYRE								80.00
A 54900099								300.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								180.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
A WHEELALIGNMENTBP								80.00
To Conduct Computerize Full Wheel Alignment								
E PNT88000								40
REMOVE & REFIT FR PARKING ASSIST SENSOR								80.00
M SUNDRY								80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								20
SUPPLY BODY PNL SEALANT								50.00
M SUNDRY								
Sundries								
M NEW K3 GRAVITY BLUE B4U	X R				1.00	1177.00	00.00	1177.00
M PANEL-FENDER,RH	DO				1.00	435.00	00.00	435.00
M GUARD ASSY-FRONT WHEEL,RH	?				1.00	95.00	00.00	95.00
M LAMP ASSY-HEAD,RH	Cut				1.00	2209.00	00.00	2209.00
M COVER-FR BUMPER	X R				1.00	633.00	00.00	633.00
M STRIP ASSY-FR BUMPER UPR	X				1.00	29.00	00.00	29.00
M BRACKET-FR BUMPER SIDE MTG,RH	?				1.00	13.00	00.00	13.00
M WHEEL ASSY-ALUMINIUM	Cut				1.00	981.00	00.00	981.00
SURVEYOR NAME: Steve (LKK)								
SURVEYOR SIGNATURE: 29/7/21, 12-30pm								
DATE: Wil P.L								
REMARKS: PIP, 4 days								
My Ref sig								

Confirm & accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on Net 11,812.00
826.84
Total Payable 12,638.84

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.