

Date: 28.07.2021

Vehicle No: SLK5659S

Model: MAZDA 3 4-DOOR SEDAN 1.5L

Chassis: JM6BN22A8H0137961

Reg. Year: 2017

Third Party Insurer: CHN TAIPING

Third Party Veh No: SLK9853X

Date of Accident: 27.07.2021

Estimator: VICTOR

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER 866.80	1	Ry	\$896.80
2	FRONT FENDER RH 360.80	1	Ry	\$380.60
3	HEADLAMP RH 1075	1	CM	\$1,090.50
4	FRONT GRILLE	1	CM Ry	\$155.50
5	FRONT GRILLE CHROME RH	1	Sm	\$191.70
6	FRONT GRILLE TOP GARNISH	1	Sm	\$379.40
7	FRONT LOWER GRILLE COVER RH	1	Ry	\$46.60
8	FOG LAMP (TURN LIGHT) RH	1	CM	\$85.00
9	FOG LAMP COVER RH	1	Myet	\$32.00
10	FRONT REINFORCEMENT	1	R	\$522.80
11	SPARE WATER TANK	1	Ry	\$89.10
12	FRONT INNER SHIELD RH	1	CM	\$111.90
13	FRONT SIDE RETAINER RH	1	CM	\$29.70
14	FRONT RIM RH	1	Sm	\$899.35
15	FRONT ABSORBER RH	1	Sm	\$377.35
16	FRONT KNUCKLE ARM RH 402.60	1	Ry	\$495.25
17	FRONT LOWER ARM RH	1	OIT	\$401.75
18	FRONT WHEEL BEARING RH	1	My	\$252.30
19	FRONT STABILIZER LINK RH	1	Sm	\$133.20
SUB TOTAL				\$6,570.80
LESS 20%				-\$1,314.16
PARTS TOTAL				\$5,256.64

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	My	\$80.00
2	FRONT GRILLE CLIPS	1	My	\$60.00
3	FRONT LOWER GRILLE CLIPS	1	My	\$50.00
4	FRONT INNER SHIELD CLIPS	1	My	\$50.00
S/N TOTAL				\$240.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST ACCIDENT AREA.

\$1,000.00

400d

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by the insurance company

Acknowledged by Repairer

Signature:

Branch (Motor Insurance Claims)

Head office

8 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

81X 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 28.07.2021
Vehicle No: SLK5659S
Model: MAZDA 3 4-DOOR SEDAN 1.5L
Chassis: JM6BN22A8H0137961
Reg. Year: 2017

Third Party Insurer: CHN TAIPING
Third Party Veh No: SLK9853X
Date of Accident: 27.07.2021
Estimator: VICTOR
Surveyor:

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.

\$1,000.00

LABOUR CHARGES TO DISMANTLE AND RE-INSTALL UNDERCARRIAGE.

\$200.00

TO CONDUCT WHEEL ALIGNMENT

\$100.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

nn \$150.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00

LABOUR TOTAL \$2,720.00

TOTAL \$8,216.64

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554800
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

