

Date: 27.07.2021

Vehicle No: SMT7002P

Model: LEXUS RX300 SUV

Chassis: JTJBAMCA702112460-2020

Reg. Year: 2020

Third Party Insurer: AIG

Third Party Veh No: GBJ3038X

Date of Accident: 20.07.2021

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		Bu \$996.00
2	REAR BUMPER LOWER LIP COVER 523	1		nd 167 \$708.00
3	REAR BUMPER GARNISH COVER LH	1		nd \$211.00
4	REAR BUMPER REFLECTOR LH	1		Ln \$75.00
5	REAR EXHAUST TAIL LH	1		Sn \$260.00
SUB TOTAL				\$2,250.00
LESS 10%				-\$225.00
PARTS TOTAL				\$2,025.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		Ln \$60.00
2	REAR BUMPER REVERSE SENSOR	1		shot \$300.00
S/N TOTAL				\$360.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$300.00 200

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC.

\$300.00 220

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 50

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 15

LABOUR TOTAL \$780.00

VIC / TING AN

TOTAL \$3,165.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1213

Fax: (+65) 6472 2112

Branch

SA Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9010 Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

