

TP AXA
Ceilin.

SMM304B.
Honda Freed Hybrid.
GB71069799.

Rear Bumper ~~Paint~~ 828.90 ✓
30(SN) X NN

Rear Bumper Clips ~~new~~ 32x2=64 X
Rear Bumper Side Holder x 2 150(SN) X
Rear Bumper Top Chrome ~~Best~~ 180(SN) X

Reverse Sensor ~~new~~ 280(SN) X
Spare Tyre Panel Undercover ~~new~~ 241.20 X

Spare Tyre Panel Undercover Clips. 30(SN) X
828.90 S.N: 150
66312

Panel Beating

Spray Painting

Wiring.

To remove cruise sensor. ~~100~~ 50

total: 1293.12

4/5: 1K.

02 Days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: