



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S 3S TRANSPORT SERVICES
Blk 647 Yishun St 61 #05-382
SINGAPORE 760647
Insured 3S TRANSPORT SERVICES
Policy VFX/P1225206/00085

Final Bill

GST Reg. No: 19-9800107D
Date: 3/8/2021
Our Case Ref. SC18/09/223/43T-TP
Accident Date 25/9/2018

Damaged Vehicle No: PC3100U

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	WORKART	1 PC	\$300.00	-	\$300.00
2	FRONT WINDSCREEN	1 PC	\$4,370.30	-	\$4,370.30
3	FRONT WINDSCREEN RUBBER	1 PC	\$262.30	-	\$262.30
4	SEALANT	8 PC	\$42.70	-	\$341.60
5	RHS WING MIRROR SET	1 PC	\$1,591.99	-	\$1,591.99
<u>Labour Charges</u>					
1	REPAIR LABOUR FOR FRONT AND RHS PORTION	1	\$2,560.00	-	\$2,560.00
2	SPRAY PAINTING FOR FRONT AND RHS PORTION	1	\$2,200.00	-	\$2,200.00
3	WIRING	1	\$80.00	-	\$80.00
4	LABOUR FOR FRONT WINDSCREEN	1	\$500.00	-	\$500.00
Sub Total					\$ 12,206.19
GST (7%)					\$ 854.43
Total Amount					\$ 13,060.62


Authorised Signature