



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S 3S TRANSPORT SERVICES
Blk 647 Yishun St 61 #05-382
SINGAPORE 760647
Insured 3S TRANSPORT SERVICES
Policy VFX/P1225206/00085

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 26/9/2018
Our Case Ref. SC18/09/223/43T-TP
Accident Date 25/9/2018

Damaged Vehicle No: PC3100U 19/01/15

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts					
1	WORKART	1 PC	\$500.00	-	300. \$500.00
2	FRONT BUMPER	1 PC	\$1,384.00	-	1,384.00 1,384.00
3	FRONT WINDSCREEN	1 PC	\$4,370.30	-	4,370.30 4,370.30
4	FRONT WINDSCREEN RUBBER	1 PC	\$262.30	-	262.30 262.30
5	SEALANT	8 PC	\$42.70	-	341.60 341.60
6	RHS WING MIRROR SET	1 PC	\$1,591.99	-	1,591.99 1,591.99
Labour Charges					
1	REPAIR LABOUR FOR FRONT AND RHS PORTION	1	\$2,500.00	-	640 2,500.00
2	SPRAY PAINTING FOR FRONT AND RHS PORTION	1	\$2,500.00	-	500-800. 2,500.00
3	WIRING	1	\$80.00	-	80.00
4	LABOUR FOR FRONT WINDSCREEN	1	\$700.00	-	500. 700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature

6866.19
5340
\$12,206.19
* 4 days

part by part.

Tanjik 97495749
WP'

28/9/18 1015
Resurvey before paint
sur@lkkauto.com
4 days.

Sub Total \$ 14,230.19