

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT21002386	Page	1
	64 CECIL STREET	Date	: 29. Jul 2021		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SKX1891G	Engine No	: R18A12048430		
Chassis No	: JHMF16307S224282	Date Time	: 29. Jul 2021 2:45:56 PM		
Model	: CIVIC 1.8L VTI-S AUTO	Surveyor Name	:		
Owner's Name	: BENNY LAW KOK LIN (LIU GUOLIN)	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 23/7/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: BENNY LAW KOK LIN						
	OWNER INSURER: BUDGET DIRECT						
	ACC DATE: 23/07/2021						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE						
	TP VEH: SLM7833G						
04715-SNB-000ZZ	FACEREAR BUMPER	1	801.90	25	601.42	42.10	643.52
91503-SZ3-003	CLIP,ABUMPER	2	3.90	25	5.85	0.41	6.26
91505-S9A-003	CLIP ABUMPER	8	3.90	25	23.40	1.64	25.04
71598-SNA-A01	SPACERL RR BPR SIDE	1	17.10	25	12.82	0.90	13.72
71593-SNA-A01	SPACERR.RR.BUMPER SIDE	1	17.10	25	12.82	0.90	13.72
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
	Sum Item				976.31	68.35	1,044.66
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BKBU02R	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON	1	800.00		800.00	56.00	856.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	600.00		600.00	42.00	642.00
	Sum Labor				1630.00	114.10	1,744.10

Survey By

Date & Time

Excess

Status

Total Amount 2,606.31 182.45 2,788.76**Total (Inclusive of GST)** **2,788.76**

Printed on 29/7/2021 3:54:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT21002386	Page	2
Registration No	: SKX1891G	Date	: 29. Jul 2021	Customer No.	: WZI007
Chassis No	: JHMF16307S224282	Svc Advisor	: RUEBEN THOMAS	Engine No	: R18A12048430
Model	: CIVIC 1.8L VTI-S AUTO	Date Time	: 29. Jul 2021 2:45:56 PM	Surveyor Name	:
Owner's Name	: BENNY LAW KOK LIN (LIU GUOLIN)	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 23/7/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
Signature							

Printed on 29/7/2021 3:54:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53,50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.