



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Acknowledged by Repairer

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKX1891G
Chassis No : JHMF16307S224282
Model : CIVIC 1.8L VTI-S AUTO
Owner's Name : BENNY LAW KOK LIN (LIU GUOLIN)
Ins Policy No :
Date of Accident : 23/7/2021

Document No. : SQT21002386
Date : 29. Jul 2021
Customer No. : WZ1007
Svc Advisor : RUEBEN THOMAS
Engine No : R18A12048430
Date | Time : 29. Jul 2021 2:45:56 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: BENNY LAW KOK LIN OWNER INSURER: BUDGET DIRECT ACC DATE: 23/07/2021 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE TP VEH: SLM7833G						
04715-SNB-000ZZ	FACEREAR BUMPER R	1	801.90	X 25	601.42	42.10	643.52
91503-SZ3-003	CLIP, ABUMPER nu	2	3.90	= 25	5.85	0.41	6.26
91505-S9A-003	CLIP ABUMPER nu	8	3.90	= 25	23.40	1.64	25.04
71598-SNA-A01	SPACERL RR BPR SIDE 11	1	17.10	X 25	12.82	0.90	13.72
71593-SNA-A01	SPACERR.RR.BUMPER SIDE 11	1	17.10	X 25	12.82	0.90	13.72
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR nu	1	320.00	X	320.00	22.40	342.40
Sum Item					976.31	68.35	1,044.66
BOSUN	SUNDRIES 11	1	50.00	X	50.00	3.50	53.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	120	180.00	12.60	192.60
BKBU02R	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON	1	800.00	650	800.00	56.00	856.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	600.00	520	600.00	42.00	642.00
Sum Labor					1630.00	114.10	1,744.10

Survey By

Date & Time

Excess

Status

Marcus Lee
10/8/21 @ 10am.
2 days.
The ph. after rep.

Total Amount 2,606.31 182.45 2,788.76

Total (Inclusive of GST) 2,788.76

Printed on 29/7/2021 3:54:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.