

TOTAL

Uhh: Ashe

Not Arrived
uncing

29/7/21

1/s \$5300 5 days.
Tel: 011-444-4444

SMF8572C Honda HR-V

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>De</i> 798.10	\$ 1,209.00 ✓
2	2	Rear bumper retainer <i>11</i>	\$ 166.00 X
3	1	Rear bumper left reflector <i>11</i>	\$ 95.00 X
4	1	Rear bumper right reflector <i>11</i>	\$ 95.00 X
5	1	Rear bumper <i>under cover</i> <i>Dis 345.20</i>	\$ 787.00 ✓
6	1	Rear bumper right side lower panel <i>NJ</i>	\$ 787.00 X
7	1	Rear left side bumper <i>De/wrapped</i> 195	\$ 355.00 ✓
8	1	Rear right side bumper <i>11</i>	\$ 355.00 X
9	1	Rear tailgate assy <i>body</i> 877.90	\$ 1,887.00 ✓
10	1	Rear tailgate weatherstrip <i>twi</i> 101.30	\$ 188.00 ✓
11	1	Rear tailgate HRV emblem <i>rec</i> 38.00	\$ 68.00 ✓
12	1	Rear tailgate IVTEC emblem <i>rec</i> 35.00	\$ 68.00 ✓
13	1	Rear tailgate centre logo <i>11</i>	\$ 68.00 X
14	1	Rear tailgate lock sensor <i>c/c</i> 85.20	\$ 289.00 ✓
15	1	Rear tailgate lock <i>Sent/twi</i> 105.40	\$ 175.00 ✓
16	1	Rear tailgate lock catch <i>11</i>	\$ 68.00 X
17	2	Rear tailgate damper <i>11</i>	\$ 276.00 X
18	2	Rear tailgate rubber stopper <i>11</i>	\$ 68.00 X
19	1	Rear tailgate inner handle <i>11</i>	\$ 88.00 X
20	1	Rear tailgate outer garnish <i>11</i>	\$ 678.00 X
21	1	Rear tailgate outer garnish chrome <i>11</i>	\$ 98.00 X
22	1	Rear tailgate inner trim board <i>De/c/c</i> 280.40	\$ 476.00 ✓
23	1	Rear left tailgate taillamp <i>c/c</i> 276.90	\$ 423.00 ✓
24	1	Rear right tailgate taillamp <i>11</i>	\$ 423.00 X
25	1	Rear left taillamp <i>c/c</i> 482.40	\$ 866.00 ✓
26	1	Rear right taillamp <i>11</i>	\$ 866.00 X
27	2	Rear no plate lamp <i>11</i>	\$ 120.00 X
28	1	Rear end lower panel top garnish <i>twi</i>	\$ 118.00 ✓
29	1	Rear end lower panel <i>body</i> 382.70	\$ 1,272.00 ✓
30	1	Rear exhaust muffler assy <i>11</i>	\$ 1,297.00 X
31	2	Rear exhaust muffler rubber mounting <i>11</i>	\$ 66.00 X
32	1	Rear floor panel <i>top board</i> <i>Torn</i> 316.00	\$ 1,670.00 ✓
33	1	Rear floor panel tools sponge <i>Torn</i>	\$ 298.00 ✓
34	1	Rear wiper blade assy <i>11</i>	\$ 166.00 X
35	1	Rear windscreen glass moulding <i>rec</i> 118.00	\$ 288.00 ✓
36	1	Rear left fender side protector <i>Torn</i> 180.10	\$ 195.00 ✓
37	1	Rear right fender side protector <i>11</i>	\$ 195.00 X
			\$ 16,607.00
less 20%			\$ 3,321.40
			\$ 13,285.60

SMF8572C Honda HR-V

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10 184	Rear bumper clips <i>all</i>	\$ 60.00 <i>40</i>
2	10 184	Rear bumper reverse sensor <i>Shorted</i>	\$ 1,200.00 <i>200</i>
3	1	Rear no plate with garnish <i>^^</i>	\$ 100.00 <i>X</i>
4	4	Rear end lower panel top garnish clips <i>^^</i>	\$ 30.00 <i>X</i>
5	1	Rear end lower panel sealant <i>all</i>	\$ 100.00 <i>50</i>
6	1	Rear windscreen glass sealant <i>all</i>	\$ 100.00 <i>40</i>
7	10 184	Rear tailgate inner trim board clips <i>all</i>	\$ 60.00 <i>45</i>
8	6	Rear tailgate outer garnish clips <i>^^</i>	\$ 40.00 <i>X</i>
9	1	Rear view camera <i>^^</i>	\$ 500.00 <i>X</i>
10	1	Rear floor panel sealant <i>^^</i>	\$ 150.00 <i>X</i>
11	1	Rear floor panel insulator pad <i>^^</i>	\$ 180.00 <i>X</i>
12	6	Rear left fender side protector clips <i>^^</i>	\$ 30.00 <i>X</i>
13	6	Rear right fender side protector clips <i>^^</i>	\$ 30.00 <i>X</i>
			<u>\$ 2,580.00</u>
Total parts			\$ 15,865.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMF8572C Honda HR-V

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,400.00	850
2	To putty and spray painting rear portion.	\$ 1,400.00	1000
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60
5	To remove and install rear exhaust muffler assy.	\$ 120.00	X
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00	80
7	To apply anti rust proofing to rear affected area.	\$ 140.00	60
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	120
10	To remove and install rear view camera.	\$ 80.00	X
11	Towing service.	\$ 100.00	X
Total labour :		\$ 3,730.00	

Total parts : \$ 15,865.60

Total labour : \$ 3,730.00

Total repair cost : \$ 19,595.60

P- 5033.60
 202
 P- 4026.88
 S.N- 375
 L- 2240
 6641.88
 8313