

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC 6/CT121008071/UC93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

219A

Vehicle: IN / OUT

Date:

Person Contacted:

21A 38338

Veh No:

SMF 8572C

Yr Regn:

27/11/18

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Honda HR-V

C.C

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

58976

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMRU 1810JX200 636

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/1/14

D.O.I.

29/1/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/8/14 Dep 9500
2/5 5300 confirmed with AH long

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

Uhh: Ashe

Not Arrived
uncing

29/7/21

1/s \$5300 5 days.
Tel: 011-444-4444

SMF8572C Honda HR-V

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>De</i> 798.10	\$ 1,209.00 ✓
2	2	Rear bumper retainer <i>11</i>	\$ 166.00 X
3	1	Rear bumper left reflector <i>11</i>	\$ 95.00 X
4	1	Rear bumper right reflector <i>11</i>	\$ 95.00 X
5	1	Rear bumper <i>under cover</i> <i>Dis 345.20</i>	\$ 787.00 ✓
6	1	Rear bumper right side lower panel <i>NJ</i>	\$ 787.00 X
7	1	Rear left side bumper <i>De/wrapped</i> 195	\$ 355.00 ✓
8	1	Rear right side bumper <i>11</i>	\$ 355.00 X
9	1	Rear tailgate assy <i>body</i> 877.90	\$ 1,887.00 ✓
10	1	Rear tailgate weatherstrip <i>twi</i> 101.30	\$ 188.00 ✓
11	1	Rear tailgate HRV emblem <i>rec</i> 38.00	\$ 68.00 ✓
12	1	Rear tailgate IVTEC emblem <i>rec</i> 35.00	\$ 68.00 ✓
13	1	Rear tailgate centre logo <i>11</i>	\$ 68.00 X
14	1	Rear tailgate lock sensor <i>c/c</i> 85.20	\$ 289.00 ✓
15	1	Rear tailgate lock <i>Sent/twi</i> 105.40	\$ 175.00 ✓
16	1	Rear tailgate lock catch <i>11</i>	\$ 68.00 X
17	2	Rear tailgate damper <i>11</i>	\$ 276.00 X
18	2	Rear tailgate rubber stopper <i>11</i>	\$ 68.00 X
19	1	Rear tailgate inner handle <i>11</i>	\$ 88.00 X
20	1	Rear tailgate outer garnish <i>11</i>	\$ 678.00 X
21	1	Rear tailgate outer garnish chrome <i>11</i>	\$ 98.00 X
22	1	Rear tailgate inner trim board <i>De/c/c</i> 280.40	\$ 476.00 ✓
23	1	Rear left tailgate taillamp <i>c/c</i> 276.90	\$ 423.00 ✓
24	1	Rear right tailgate taillamp <i>11</i>	\$ 423.00 X
25	1	Rear left taillamp <i>c/c</i> 482.40	\$ 866.00 ✓
26	1	Rear right taillamp <i>11</i>	\$ 866.00 X
27	2	Rear no plate lamp <i>11</i>	\$ 120.00 X
28	1	Rear end lower panel top garnish <i>twi</i>	\$ 118.00 ✓
29	1	Rear end lower panel <i>body</i> 382.70	\$ 1,272.00 ✓
30	1	Rear exhaust muffler assy <i>11</i>	\$ 1,297.00 X
31	2	Rear exhaust muffler rubber mounting <i>11</i>	\$ 66.00 X
32	1	Rear floor panel <i>top board</i> <i>Torn</i> 316.00	\$ 1,670.00 ✓
33	1	Rear floor panel tools sponge <i>Torn</i>	\$ 298.00 ✓
34	1	Rear wiper blade assy <i>11</i>	\$ 166.00 X
35	1	Rear windscreen glass moulding <i>rec</i> 118.00	\$ 288.00 ✓
36	1	Rear left fender side protector <i>Torn</i> 180.10	\$ 195.00 ✓
37	1	Rear right fender side protector <i>11</i>	\$ 195.00 X
			\$ 16,607.00
less 20%			\$ 3,321.40
			\$ 13,285.60

SMF8572C Honda HR-V

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10 184	Rear bumper clips <i>all</i>	\$ 60.00 <i>40</i>
2	10 184	Rear bumper reverse sensor <i>Shorted</i>	\$ 1,200.00 <i>200</i>
3	1	Rear no plate with garnish <i>^^</i>	\$ 100.00 <i>X</i>
4	4	Rear end lower panel top garnish clips <i>^^</i>	\$ 30.00 <i>X</i>
5	1	Rear end lower panel sealant <i>all</i>	\$ 100.00 <i>50</i>
6	1	Rear windscreen glass sealant <i>all</i>	\$ 100.00 <i>40</i>
7	10 184	Rear tailgate inner trim board clips <i>all</i>	\$ 60.00 <i>45</i>
8	6	Rear tailgate outer garnish clips <i>^^</i>	\$ 40.00 <i>X</i>
9	1	Rear view camera <i>^^</i>	\$ 500.00 <i>X</i>
10	1	Rear floor panel sealant <i>^^</i>	\$ 150.00 <i>X</i>
11	1	Rear floor panel insulator pad <i>^^</i>	\$ 180.00 <i>X</i>
12	6	Rear left fender side protector clips <i>^^</i>	\$ 30.00 <i>X</i>
13	6	Rear right fender side protector clips <i>^^</i>	\$ 30.00 <i>X</i>
			<u>\$ 2,580.00</u>
Total parts			\$ 15,865.60

SMF8572C Honda HR-V

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,400.00	850
2	To putty and spray painting rear portion.	\$ 1,400.00	1000
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60
5	To remove and install rear exhaust muffler assy.	\$ 120.00	X
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00	80
7	To apply anti rust proofing to rear affected area.	\$ 140.00	60
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	120
10	To remove and install rear view camera.	\$ 80.00	X
11	Towing service.	\$ 100.00	X
Total labour :		\$ 3,730.00	

Total parts : \$ 15,865.60

Total labour : \$ 3,730.00

Total repair cost : \$ 19,595.60

P- 5033.60
 202
 P- 4026.88
 S.N- 375
 L- 2240
 6641.88
 8313